

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD

EVANSVILLE, IN 47725
USA

Labor rate: \$150.00
OWNER INFORMATION

CLAIM STATUS Authorized
CLAIM 953711
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CKEC3NY023732
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 017 / 017D
ITEM # CKTR16BHS-D
DEALER RO # 66650
CLAIM START DATE 03/07/2022
CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor
Line# 1 Operation Code Operational Description
40-112-24-11-001350 Monitor Panel Wiring or Harness - Electrical/Monitor Panel/Repair/
Electrical

Complaint, Cause, Correction
Original Note : parts@americanrvcenter.com, 2022-03-07 15:36:09 :: BLACK TANK READS FULL WHEN
EMPTY Additional Note : parts@americanrvcenter.com, 2022-03-07 15:43:21 :: BROWN WIRE GOING TO
MONITOR PANEL SHORTED IN THE CEILING. Additional Note : parts@americanrvcenter.com, 2022-03-07
15:49:50 :: CORRECTION: RAN NEW WIRE FROM THE CONTROL MODULE TO THE BLACK WATER TANK.
HAD TO DRILL NEW HOLE THROUGH CABINETS TO RUN THE NEW WIRE. CUT A NEW PIECE OF
WOODGRAIN PANEL TO SIZE AND USED IT TO COVER HOLES AND NEW WIRING IN CABINET.

Model #	Dlr Sub Hrs	6.50	Sub Labor Amt	\$975.00
Serial #	Appr Hrs	3.50	Appr Labor Amt	\$525.00

Notes

Submitted	Labor Amt	\$975.00	Approved	Labor Amt	\$525.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$975.00		Total	\$525.00

DEALER _____ DATE _____
SIGNATURE
I certify that I have performed these repairs consistent with Forest
River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
All repairs described have been inspected and are satisfactory.