

WORK ORDER # 66650

```

Completed : 17 MAR 22      Customer : 1009 - FOREST RIVER INC. -
Licence # :                Invoice # :
Stock No : 10891          Description : 2022 TT FOREST RIVER CHEROKEE WOLF
Tag :                     Date In : 03 MAR 22      Mileage :
Author : DH               Promised : 26 MAR 22
Location : 0318 SEE IF BH CAN Date Sched :
Serial# : 5ZT2CKEC3NY023732 Chassis# : 5ZT2CKEC3NY023732
Warr. Date :              Cust PO# :
Print Date : 17 MAR 22

```

Job #	Description	JOB INFORMATION	Type	Bill To	
SUMM	COMPLAINT: SUMMERLAND PDI CORRECTION: PREFORMED A PDI OM NEW TRAVEL TRAILER ON 3/4/22, EVERYTHING IS WORKING AS OF THE TIME OF THE PDI ON 3/4/22		I	PDI	PRE-D
WINT	COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS. ***INCLUDES 2 GALLONS OF ANTI-FREEZE*** UNITS WITH WASHING MACHINE OR ICEMAKER WILL BE EXTRA **DE-WINTERIZATION IS NOT INCLUDED** CORRECTION: WINTERIZED NEW UNIT ON 3/4/22		I	PDI	PRE-D
1	COMPLAINT: BLACK TANK READS FULL BUT IS EMPTY CAUSE: BLACK TANK WAS READING FULL WHEN EMPTY, DUE TO STAPLE OR NAIL THROUGH WIRE DONE BY THE MANUFACTURE. YOU COULNDT EVEN MOVE OLD WIRE IT WAS STUCK IN PLACE. BECAUSE OF THIS CAUSED A FALSE READING TO READ FULL WHEN EMPTY CORRECTION: AFTER TRYING TO TRACE THE OLD WIRE FROM THE MODULE PANEL TO THE TANK THAT RAN THROUHOUT THE CELLING. WE HAD TO REVOME FRIDGE, MICROWAVE, AND CONVERTER AND HAD TO DRILL HOLES THROUGH CABNIET COMPARTMENTS TO RUN THE NEW WIRE. WE RAN THE NEW WIRE FROM THE CONTROL MODULE THROUGH THE CABNIETS AND DOWN THE FLOOR WHERE THE FRIDGE IS AND DOWN AND OUT TO THE TANK. THIS FIXED THE PROBLEM AND IS READING CORRECTLY. NEW WIRE FROM THE CONTROL MODULE TO THE BLACK WATER TANK. THROUGH CABNIETS TO RUN THE NEW WIRE. DUE TO THE NEW HOLES I HAD TO MAKE A NEW PANEL TO COVER UP EXPOSED WIRE IN CABNIET.		W	1009	FORES

Work Order : 66650

```

*****
Job # Part No Description          PARTS          Bill to  Qty      Price      Total
*****
SUMME 13034  55362 STD BATTERY BOX      I-PDI        0      10.99      0.00
SUMME DC-24  ADVANCE GROUP 24 DEEP CYCLE B I-PDI        0     126.99      0.00
WINTE 24181  -50 RV ANTI-FREEZE GALLON      I-PDI        2       4.49      8.98
*****

```

```

*****
Job#  Lab Code  Description          LABOUR      Mech Bill to  Hrs      Rate      Total
*****
RLAND Z990      MISC LABOUR CODE (EXTE RAB I-PDI        3.90     150.00     585.00
RLAND Z990      MISC LABOUR CODE (EXTE RAB I-PDI        0.60     150.00      90.00
INTER Z990      WINTERIZE UNIT          RAB I-PDI        1.00     130.00     130.00
  1 Z990      MISC LABOR CODE          RAB W-1009    0.20     150.00      30.00
  1 Z990      MISC LABOR CODE          RAB W-1009    0.30     150.00      45.00
  1 Z990      MISC LABOR CODE          RAB W-1009    2.00     150.00     300.00
  1 Z990      MISC LABOR CODE          BRM W-1009    1.00     150.00     150.00
*****

```

```

*****
Job #  Excode   Description          EXTRAS          bill to  Qty      Price      Total
*****
RLAND  LPG      LP GAS              I-PDI        4.00       3.99     15.96
INTER  SS       SHOP SUPPLIES      I-PDI        1.00       9.70      9.70
*****

```

```

*****
                        CUSTOMER COMMENTS
*****
APPROVED 3.5 HOURS ON AUTH #953711
*****

```

```

*****
                        BILLINGS SUMMARY
Type Bill Id          Parts      Labour      Sublet      Extras      Tax      Total
*****
I    PDI              8.98      805.00      0.00      25.66      0.00      839.64
W    1009             0.00      525.00      0.00       0.00      0.00      525.00
Totals              8.98     1330.00      0.00      25.66      0.00     1,364.64
*****

```