

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66652

Completed : 25 MAR 22 Customer : 10024 - FOREST RIVER TRAVEL TRAILER
 Licence # : Invoice # :
 Stock No : 11091 Description : 2022 TT COACHMEN CATALINA 283RKSLE
 Tag : Date In : 03 MAR 22 Mileage : 0
 Author : BH Promised : 26 MAR 22
 Location : 0325 SEE IF WO CAN Date Sched :
 Serial# : 5ZT2CATB4NX025628 Chassis# : 5ZT2CATB4NX025628
 Warr. Date : Cust PO# :
 Print Date : 25 MAR 22

```

*****
Job #   Description          JOB INFORMATION          Type Bill To
*****
PDIN    COMPLAINT:  Transferred to BAS*66728 on 11 MAR 22   I   PDI   PRE-D
        Estimate amount was 0.00 PDI - NEW
        TRAVEL TRAILER
        CORRECTION:  FIND UNIT, CLOAE UP BRING IN, CHECK
        LIGHTS TIERS. LUG NUTS GET AND INSTALL
        BATTERY BOX, FILL LP TANKS ( 2  20 lbs)
        CHECK ROOF BRAKES, FILL WATER TANKS,
        CHECK WATER SYSTEM ( BATHROOM SINK IS
        SLOW DRAINING) CHECK TV ( TV HAS LINES
        IN SCREEN AND WILL NOT PICK STATIONS)
        FURNACE RADIO, RANGE,WATER HEATER,
WINT    COMPLAINT:  Transferred to BAS*66728 on 11 MAR 22   I   PDI   PRE-D
        Estimate amount was 0.00 WINTERIZE UNIT
        AND DRAIN HOLDING TANKS. ***INCLUDES 2
        GALLONS OF ANTI-FREEZE*** UNITS WITH
        WASHING MACHINE OR ICEMAKER WILL BE
        EXTRA **DE-WINTERIZATION IS NOT
        INCLUDED**
        CORRECTION:  drain tanks, blow out water lines, pump
        in atifrezze
1      COMPLAINT:  TV HAS A BAD SCREEN IN THE LIVING ROOM   W   10024  FORES
        CAUSE:      BAD SPOT IN THE TV
        CORRECTION:  NEED TO REPLACE THE TV
2      COMPLAINT:  BATHROOM SINK DRAINS VERY SLOW           W   10024  FORES
        CAUSE:      sink takes 3 minnets to drain, drain
        line is running up befor dropping
        CORRECTION:  remove P trap check run bore scope thru
        lines to check that they are open,
        remove bathroom door, door frame and
        wall board in hallway to gain access to
        pulmbing lines, found , drain line is
        running up befor dropping down to line
        to gray tank, cut drain line to tank in
        wall below and above T fitting install
  
```

Work Order : 66652

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
                                new T fitting, new elbow short line and
                                threede fitting to sink, install shot
                                setion of pipe above T fitting and
                                connet up to vent line, water test for
                                leaks, sink drains normal, pull staples
                                and put wall back together, install door
                                frame and door

```

```

*****
Job # Part No   Description                PARTS                Bill to   Qty   Price   Total
*****
PDINT 13034     55362 STD BATTERY BOX      I-PDI         0     10.95   0.00
WINTE 24181     -50 RV ANTI-FREEZE GALLON I-PDI         0     4.49   0.00
2      89-8095      TEE (T-4) 1 1/2"          W-10024       1     1.81   1.81
2      602391      632871 1-1/2" MALE ADAPTER W-10024       1     1.31   1.31
2      89-8002      COUPLING 1 1/2" H X H     W-10024       1     1.37   1.37
2      100825      Fitting - ABS - Str Elbow W-10024       1     1.14   1.14
1      F100284357 39" TV LED CX39A21        W-10024       1    396.58 396.58

```

```

*****
Job# Lab Code Description                LABOUR Mech Bill to   Hrs   Rate   Total
*****
DINTT Z991     MISC LABOUR CODE (INTE JP I-PDI         0.00  150.00 0.00
DINTT Z991     MISC LABOUR CODE (INTE JP I-PDI         0.00  150.00 0.00
DINTT Z991     MISC LABOUR CODE (INTE JP I-PDI         0.00  150.00 0.00
DINTT Z991     MISC LABOUR CODE (INTE JP I-PDI         0.00  150.00 0.00
INTER Z990     WINTERIZE UNIT           JP I-PDI         0.00  130.00 0.00
INTER Z990     WINTERIZE UNIT           JP I-PDI         0.00  130.00 0.00
1 Z990     MISC LABOUR CODE (EXTE JP W-10024       0.00  150.00 0.00
1 Z990     MISC LABOUR CODE (EXTE JP W-10024       0.30  150.00 45.00
2 Z990     MISC LABOUR CODE (EXTE JP W-10024       2.00  150.00 300.00
2 Z990     MISC LABOUR CODE (EXTE JP W-10024       2.00  150.00 300.00
2 Z990     MISC LABOUR CODE (EXTE JP W-10024       0.00  150.00 0.00

```

```

*****
Job # Excode   Description                EXTRAS                bill to   Qty   Price   Total
*****
DINTT SS       SHOP SUPPLIES              I-PDI         0.00  35.00   0.00
DINTT LPGI     LP - UNIT SALES            I-PDI         0.00   3.99   0.00
INTER SS       SHOP SUPPLIES              I-PDI         0.00   9.70   0.00
1 FRT         UPS-TV                      W-10024       1.00  33.80  33.80

```

CUSTOMER COMMENTS

```

*****
RO IS READY TO CLOSE WAITING ON BILLING
TV ARRIVED IN BACKROOM W/OUT INVOICING 3-16-22...CAM
ORDERED TV PER BEN.

```

Continued on page 3

Work Order : 66652

BH SENT IN PREAUTH

BILLINGS SUMMARY

Type	Bill Id	Parts	Labour	Sublet	Extras	Tax	Total
W	10024	402.21	645.00	0.00	33.80	0.00	1,081.01
	Totals	402.21	645.00	0.00	33.80	0.00	1,081.01