

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66669
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 36923 - DONNY L. HARMS
Address: 8152 N. 2100 LANE MOUNT CARMEL, IL

62863

Phone: 812-304-0413

Stock Number: 10958 - 2021 COUGAR 290RLS 4YDF29029M2512373

VIN: 4YDF29029M2512373 HIN:

SER#: 4YDF29029M2512373

Mileage: 0

Work Order Comp: 17 MAR 22

Auth. No:

Dealer #: 1194

Warr. Date: 17 JUL 21

Work Order Date: 04 MAR 22

Inv #: 374004

WO # Job # Description JOB INFORMATION

66669 4 LOCK ON DOORSIDE FRONT COMP LOCK FLAPPER STUCK AND KEY WOULD NOT
GO IN
PUT IN A PO FOR NEW LATCH AND LOCK

66669 5 GUTTER SPOUT OFF
REMOVED SCREWS THERE WAS NO BROKEN PIECES OF A GUTTER SPOUT.
MAYBE IT WAS JUST SILICONED ON. PUT A NEW GUTTER SPOUT ON PUT
SCREWS BACK IN TOUCHED UP WITH SILICONE

66669 3 INSERT MOLDING COMING OFF ON FRONT OVERHANG
REMOVED THE SCREW AND ADJUSTED THE INSERT PUT IT BACK IN TRIM PUT
SCREW BACK IN

Part No Job# Description PARTS Qty Price Total

672831 4 Door - Baggage - A 1.00 18.03 18.03
5569 5 94174 BLK LONG RAIN GUTTER SPOUT 1.00 5.61 5.61

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 4 MISCELLANEOUS REPAIR 0.00 150.00 0.00
Z990 4 MISCELLANEOUS REPAIR 0.20 150.00 30.00
Z990 4 MISCELLANEOUS REPAIR 0.00 150.00 0.00
Z990 5 MISCELLANEOUS REPAIR 0.20 150.00 30.00
Z990 3 MISCELLANEOUS REPAIR 0.30 150.00 45.00

Claim : 66669

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT        4    UPS-LOCK                1.00      11.76      11.76

```

```

Parts Total:      23.64
Labour Total:     105.00
Sublet Total:       0.00
Extras Total:      11.76

```

```

>>>> Claim Total:      140.40

```

Customer Signature: _____

Date: _____