1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$744.65

RO# : 40942 Tag# : SJ970896

Check-in: Thu Jun 11, 2026 | 8:12 AM
Ready for Pickup: Mon Jun 22, 2026 | 2:34 PM
Promise Time: Tue Jun 16, 2026 | 6:00 PM

Customer
Chad Shurter
1243472
+1 - (907) 669 - 0174
chadpshurter@gmail.com
Little Valley Road
Spooner, WI 54801

Pickup-Customer
Same as Customer

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE KODIAK 241BHSL
4YDTKDL21*SJ970896*
1 Mi In / 1 Mi Out
Sold Date: 01/14/2026
Stock #: KS25-05

Service Advisor
BONNIE SEEMANN
bonnie

A.	**MISCELLANEOUS**	**CUSTOMER STATES BLACK TANK GATE HANDLE WON'T PUSH IN OR CLOSE ALL THE WAY.**	**Warranty Pay**	**$706.84**

Job added by BONNIE SEEMANN on Thu Jun 11, 2026 | 8:12 AM

1. Blank tank gate valve is stuck half open. T handle rod is bent and cable is binding.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $610.50

Labor Cost: $111.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	3.61	3.7	3.7	$610.50	$111.00

1. Replaced black tank gate valve.

Parts

Parts Total Sale Amount $96.34
Parts Total Cost Amount $74.11

Name	Quantity	Unit Price	Sale Price	Cost Price
0326918 - VALVE,3" 150" CABLE	1	$96.34	$96.34	$74.11

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$610.50	$111.00	$96.34	$74.11

B.	**MISCELLANEOUS**	**CUSTOMER STATES THE SEWER CAP HAS A BROKEN TAB.**	**Warranty Pay**	**$4.81**

Job added by BONNIE SEEMANN on Thu Jun 11, 2026 | 8:12 AM

1. Sewer cap broken, fell off while driving down the road.

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$744.65

RO# : 40942 Tag# : SJ970896

Check-in: Thu Jun 11, 2026 | 8:12 AM
Ready for Pickup: Mon Jun 22, 2026 | 2:34 PM
Promise Time: Tue Jun 16, 2026 | 6:00 PM

Customer
Chad Shurter
1243472
+1 - (907) 669 - 0174

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE KODIAK 241BHSL
4YDTKDL21*SJ970896*

Service Advisor
BONNIE SEEMANN
bonnie

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $0.00

Labor Cost: $0.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.06	0	0	$0.00	$0.00

1. Replaced sewer cap.

Parts

Parts Total Sale Amount $4.81

Parts Total Cost Amount $3.70

Name	Quantity	Unit Price	Sale Price	Cost Price
VLPT1020VP - WASTE VALVE CAP, 3IN BAYONET, BLACK, CARDED	1	$4.81	$4.81	$3.70

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$0.00	$0.00	$4.81	$3.70

C. MISCELLANEOUS **CUSTOMER STATES NEEDS SEVERAL SCREWS FELL OUT FROM DRIVERS SIDE FENDERSKIRT.** **Warranty Pay** **$33.00**

Job added by BONNIE SEEMANN on Thu Jun 11, 2026 | 8:12 AM

1. Self tapping screws in thin sheet metal keep falling out.

Op.1 MISCELLANEOUS -MISCELLANEOUS

Labor Sale: $33.00

Labor Cost: $6.00

Technician	Certification Number	Actual Hours	Assigned Bill Hours	Flag Hours	Labor Sale	Labor Cost
shurterc	-	0.19	0.2	0.2	$33.00	$6.00

1. Replaced screws and added small plastic backing plate to give them a little something more to grab onto

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$744.65

RO# : 40942 Tag# : SJ970896

Check-in: Thu Jun 11, 2026 | 8:12 AM
Ready for Pickup: Mon Jun 22, 2026 | 2:34 PM
Promise Time: Tue Jun 16, 2026 | 6:00 PM

Customer
Chad Shurter
1243472
+1 - (907) 669 - 0174

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE KODIAK 241BHSL
4YDTKDL21*SJ970896*

Service Advisor
BONNIE SEEMANN
bonnie

Total Labor Sale	Total Labor Cost	Total Parts Sale	Total Parts Cost
$33.00	$6.00	$0.00	$0.00

Additional Fees	Sale Amount	Cost Amount
SSC - Shop Supply Charges	$0.00	$0.00

Category	Sale	Cost
Labor	**$643.50**	**$117.00**
Parts	**$101.15**	**$77.81**
Sublet	**$0.00**	**$0.00**
Sublet Labor	**$0.00**	**$0.00**
Sublet Parts	**$0.00**	**$0.00**
Fees	**$0.00**	**$0.00**
Discounts	**$0.00**	-
Tax	**$0.00**	-
Deductible	**$0.00**	-
Insurance/Warranty	**$0.00**	-
Invoice Total	**$744.65**	**$194.81**

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
B	MISC	Fri Jun 12, 2026	12:05 PM	12:09 PM	0.06 hrs	W	shurterc	0 hrs
Tag: Regular Hour			**Reason:** -					
C	MISC	Fri Jun 12, 2026	12:10 PM	12:21 PM	0.19 hrs	W	shurterc	0.2 hrs
Tag: Regular Hour			**Reason:** -					
C	MISC	Fri Jun 12, 2026	12:23 PM	12:23 PM	0 hrs	W	shurterc	-
Tag: Regular Hour			**Reason:** -					

© Tekion Corp 2026

1025 WI-77 Minong WI US 54859 www.linkrvdirect.com

Invoice
$744.65

RO# : 40942 Tag# : SJ970896

Check-in: Thu Jun 11, 2026 | 8:12 AM
Ready for Pickup: Mon Jun 22, 2026 | 2:34 PM
Promise Time: Tue Jun 16, 2026 | 6:00 PM

Customer
Chad Shurter
1243472
+1 - (907) 669 - 0174

Billing-Customer
Same as Customer

Vehicle
2025 KEYSTONE KODIAK 241BHSL
4YDTKDL21*SJ970896*

Service Advisor
BONNIE SEEMANN
bonnie

Clock In Info

#	Opcode	Date	Clock In	Clock Out	Time Spent	Pay Type	Technician	Flag Hrs
A	MISC	Fri Jun 12, 2026	12:23 PM	12:51 PM	0.46 hrs	W	shurterc	3.7 hrs
Tag: Regular Hour			**Reason:** -					
A	MISC	Fri Jun 12, 2026	1:25 PM	4:34 PM	3.15 hrs	W	shurterc	-
Tag: Regular Hour			**Reason:** Employee shift is ended					

Accounting Info - Warranty

GL Account #	Control #	Franchise	Amount
11400	40942	LINK RV	$744.65
57200	40942	LINK RV	-$643.50
67200	40942	LINK RV	$117.00
14400	shurterc	LINK RV	-$117.00
54200	40942	LINK RV	-$101.15
64000	40942	LINK RV	$77.81
14000	40942	LINK RV	-$77.81

© Tekion Corp 2026