



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 66774
Promise Date: 26 MAR 22

CUSTOMER WORK ORDER

WO #: 66774 (Appointment Date: 16 MAR 2022 - Time: 07:00am)

Customer: 11546 - PRESKE, JOHN L. -
812-431-2790

Tag: UNIT NOT HERE AS OF 03/29/22

Author: BJW

Location: 0517 HAVE BH CLOSE THIS

Stock #: 10723

Stock Desc: (10723) 2021 KEYSTONE
SPRINGDALE 1740RK

Chassis #: 4YDT17418MW113359

Serial #: 4YDT17418MW113359

Mileage:

Licence:

Invoice #:

Date In: 16 MAR 22

Promised: 26 MAR 22

Date Sched:

Completed: 17 MAY 22

Warr. Date: 11 SEP 21

Job #1 - Warranty

COMPLAINT: COOK TOP IS NEVER LEVEL. IT IS BENT DOWN IN THE MIDDLE.

CAUSE: COOKTOP IS BENT NEED TO REPLACE

CORRECTION: BH INSTALLED COOK TOP

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR		0.00
Z990	MISCELLANEOUS REPAIR	ZMS	37.50
Z990	MISCELLANEOUS REPAIR	ZMS	37.50

Parts

Part #	Description	Qty	Price	Total
641682	Range - Top Only -	1.00	27.73	27.73

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-COOKTOP	1.00	15.69	15.69

Subtotal for Job #1: 118.42

Job #2 - Warranty

COMPLAINT: NIGHTSTAND DOORS WONT SHUT

CAUSE: BRACE THAT HOLDS DRAWES CAME APART. SCREWS THAT HELD BRACE STRIPPED OUT.

CORRECTION: TOOK 2 WIDER SCREWS AND SECURED BRACE TO THE BOTTOM OF THE SHELF.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	15.00

Subtotal for Job #2: 15.00

Job #3 - Warranty

COMPLAINT: TRIM COMING OFF OF THE SLIDE ROOM. THIS IS JUST TO THE LEFT OF THE ENTRY DOOR AND OVER THE DINING AREA.

CAUSE: trim fell off

CORRECTION: secured with staples.

Labor



Customer #: 11546
PRESKE, JOHN L.



W/O: 664
 Promise Date: 26 MAR 22

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	15.00

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #3: 15.00

Job #4 - Internal

COMPLAINT: CUSTOMER STATES THAT THE PAINT IS COMING OFF OF THE STABILIZER JACKS.

CAUSE: replace stab jacks

CORRECTION: original stab jacks were secured with self tapping screws and were also welded onto the frame. removed screws, took a grinder and cut the welds on all 4 jacks. took black spray paint and painted where i cut welds. secured stab jack to frame with self tapping screws. parked unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
285326	24IN SCISSOR JACK	2.00	N/C	N/C

Subtotal for Job #4: 0.00

Parts Total: 27.73
 Labour Total: 105.00
 Sublet Total: 0.00
 Extras Total: 15.69
WORK ORDER TOTAL: 148.42

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 17 May 2022



Customer #: 11546
 PRESKE, JOHN L.

