

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
 600 E. Baseline Rd.
 Evansville IN
 US
 47725
 812-867-5200

WORK ORDER # 66832

Completed : 31 MAR 22 Customer : 1013 - KEYSTONE RV CO -
 Licence # : Invoice # :
 Stock No : 11056 Description : 2022 TT KEYSTONE SPRINGDALE 293RK
 Tag : Date In : 21 MAR 22 Mileage :
 Author : BH Promised : 25 MAR 22
 Location : 0331 CHECK PREAUTH Date Sched :
 Serial# : 4YDTSGN26N3102660 Chassis# : 4YDTSGN26N3102660
 Warr. Date : 25 MAR 22 Cust PO# :
 Print Date : 31 MAR 22

```

*****
Job #   Description                JOB INFORMATION                Type Bill To
*****
FPDI    COMPLAINT:  FINAL PDI ON NEW TRAVEL TRAILERS                I    PDI    PRE-D
        CAUSE:      FPDINTT - FINAL PDI ON NEW TRAVEL
                   TRAILER.
        CORRECTION: Moved unit into shop from sales lot.
                   Checked all exterior lights and brakes.
                   Checked lug nuts and set tire pressure
                   at 80 psi. Recorded all tire serial
                   numbers. Checked awning. Checked all
                   interior lights. Checked all
                   appliances. Performed LP drop test and
                   set LP pressure at 11 in.wc. Checked TV
                   Antenna, TV, Radio and fireplace.
                   Tightened mounting screws on entrance
                   screen door. Moved unit to wash bay
                   area.

EQUA    COMPLAINT:  INSTALL 1000# EQUALIZER HITCH                I    DO    DEALE
        CAUSE:      EQUALIZER 1000 - INSTALL 1000# EQUALIZER
                   HITCH.
        CORRECTION: Mounted brackets on frame of unit. Set
                   hitch height on tow vehicle.

DELU    DELUXE STARTER KIT                I    DO    DEALE
PART    COMPLAINT:  MODEN / GATEWAY FOR WIFI PREP                I    DO    DEALE
        CAUSE:      PARTS - MODEM / GATEWAY FOR WIFI PREP.
        CORRECTION: Removed cover over factory hole cut in
                   ceiling. Hole too close to AC ceiling
                   outlet to allow router to be mounter
                   correctly. Elongated hole away from
                   ceiling vent. Mounted ceiling plate
                   over hole. Pulled power wires out of
                   ceiling hole. Spliced in power wires to
                   ceiling router. Connected other wires
                   to router. Mounted ceiling router to
                   ceiling plate.

BCWT    COMPLAINT:  BRAKE CONTROL & WIRING - PICKUP TRUCK        I    DO    DEALE
  
```

Continued on page 2

Work Order : 66832

 Job # Description JOB INFORMATION Type Bill To

ONLY
 CORRECTION: INSTALLED BRAKE CONTROL AND WIRING. USED
 OEM HARNESS AND TESTED 7-WAY OUTPUT.
 WALK COMPLAINT: WALK THRU I PDI PRE-D
 CORRECTION: PULLED CAMPER FROM WASH BAY AND SET UP
 IN WALK THRU AREA.DID WALK THRU SHOWED
 HITCH AND MOVED CAMPER TO STORAGE HE IS
 STORING IT HERE.
 1 COMPLAINT: THE ENTRANCE DOOR WILL NOT LATCH CLOSED. W 1013 KEYST
 CAUSE: THE ENTRANCE DOOR WILL NOT LATCH CLOSED.
 CORRECTION: Entrance door not latching when closed.
 Adjusted latch plate out to let door
 plunger grab. Checked operation of door
 closing.

Job #	Part No	Description	PARTS	Bill to	Qty	Price	Total
FPDIN	DC-24	ADVANCE GROUP 24 D		I-PDI	1	131.99	131.99
FPDIN	5516	A10-3050FHVP 30M-5		I-PDI	1	23.99	23.99
FPDIN	C01263700	RUBBER STRAP SHOWER, RADIUS		I-PDI	1	2.99	2.99
EQUAL	710831	EQUALIZER 1000#/10		I-DO	1	677.95	677.95
DELUX	44722	DELUXE STARTER KIT		I-DO	1	137.99	137.99
PARTS	GW-1000	WINEGARD GATEWAY 4		I-DO	1	308.99	308.99
BCWT	14636	7WAY PLASTIC CAR END		I-DO	0	8.99	0.00
BCWT	19-0938	9 WAY CONNECTOR - BRACKET		I-DO	0	1.99	0.00
BCWT	19-1441	16-3030 30A CIRCUIT BREAKER		I-DO	0	5.99	0.00
BCWT	51140	PROPORTIONAL BRAKE		I-DO	1	126.99	126.99

Job#	Lab Code	Description	LABOUR	Mech	Bill to	Hrs	Rate	Total
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL DKM			I-PDI	0.00	150.00	0.00
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL DKM			I-PDI	1.86	150.00	279.00
DINTT	PDINTT	PDI - NEW TRAVEL TRAIL DKM			I-PDI	0.14	150.00	21.00
R1000	Z990	MISC LABOUR CODE (EXTE DKM			I-DO	1.08	105.00	113.40
R1000	Z990	MISC LABOUR CODE (EXTE DKM			I-DO	0.41	105.00	43.05
R1000	Z990	MISC LABOUR CODE (EXTE DKM			I-DO	0.01	105.00	1.05
PARTS	Z990	MISC LABOUR CODE (EXTE DKM			I-DO	1.50	150.00	225.00
BCWT	BCWT	BRAKE CONTROL & WIRING GAH			I-DO	2.00	105.00	210.00
WALK	Z990	MISC LABOUR CODE (EXTE DGH			I-PDI	1.88	150.00	282.00
WALK	Z990	MISC LABOUR CODE (EXTE DGH			I-PDI	0.18	150.00	27.00
WALK	Z990	MISC LABOUR CODE (EXTE DGH			I-PDI	0.53	150.00	79.50
1	Z990	MISCELLANEOUS REPAIR DKM			W-1013	0.20	150.00	30.00

Job #	Excode	Description	EXTRAS	bill to	Qty	Price	Total
R1000	SS	SHOP SUPPLIES		I-DO	1.00	11.25	11.25

Continued on page 3

Work Order : 66832

```
*****
Job #  Excode   Description  EXTRAS      bill to    Qty   Price   Total
*****
BCWT  SS        SHOP SUPPLIES      I-DO        1.00   20.00   20.00
*****
```

CUSTOMER COMMENTS

```
*****
DELUXE KIT AND WIFI ROUTER IN SHOP ON RACK B SIDE...CAM 3-21-22
*****
```

BILLINGS SUMMARY

```
*****
Type Bill Id      Parts   Labour   Sublet   Extras   Tax     Total
*****
I    DO           1251.92  592.50   0.00    31.25   0.00    1,875.67
I    PDI           158.97  688.50   0.00    0.00    0.00    847.47
W    1013           0.00    30.00   0.00    0.00    0.00    30.00

Totals           1410.89 1311.00   0.00    31.25   0.00    2,753.14
*****
```