

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 66863
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 51988 - DOUGLAS PARKER
Address: 5490 HWY 66 POSEYVILLE, IN

47633

Phone: 812-307-0157

Stock Number: 11062 - 2022 MONTANA 3781RL 4YDFM0T27N4700932

VIN: 4YDFM0T27N4700932 HIN: SER#: 4YDFM0T27N4700932

Mileage: 0 Work Order Comp: 26 APR 22

Auth. No: Dealer #: 1194

Warr. Date: 07 JAN 22 Work Order Date: 23 MAR 22 Inv #: 376386

WO # Job # Description JOB INFORMATION

66863 6 THE CABINET DOOR FOR THE WASHER AND DRYER IS NOT STRAIGHT NEEDS
ADJ DOOR TO THE RIGHT AS SOON AS YOU WALK IN
door is warped and pushes out at the bottom. cant pull the hinge
in enough at the bottom to correct. need to order another door to
fix.

66863 21 BEDROOM PULL OUT DRAWER DOE NOT SLOW CLOSE DOES NOT STAY CLOSED

66863 22 TRIM ON THE STEPS TO THE BED ROOM IS LOOSE
TRIM ON BOTH SIDES OF STEPS CAME OFF.
SECURED TRIM WITH STAPLES AND FILLED HOLES WITH PUTTY

66863 23 WALL PAPER NEAR THE STEPS IS PULLING APART

66863 24 LOCK FOR THE LEVELING WILL NOT UNLOCK
HAD TO DRILL OUT THE LOCK CYLINDER TO RAISE TRAILER OFF OF TRUCK
REMOVED LOCK, WENT AND GOT REPLACEMENT LOCK, INSTALLED NEW LOCK

66863 3 KITCHEN SINNK LINK UNDER THE SINK COULD NOT FIND OUT WHERE IT IS
LEAKING BUT FIND WATER UNDER AND HAS DISCOLORED THE FLOOR
hooked up to city water. filled up both sinks halfway and let
sit. left sink is leaking where the drain line screws into the
bottom of the sink.
removed drain line and removed gasket to inspect. gasket looks
good. reset gasket in drain line and filled sink with water to
test. drain line is still leaking. removed drain line, removed

Part No	Job#	Description	PARTS	Qty	Price	Total
541759	6	Passage - Door - 2		1.00	364.37	364.37
665163	21	Drawer - Cabinet -		2.00	5.34	10.68
665164	21	CABINET SLIDE 12"		2.00	1.04	2.08
84653	22	Seam - Tape - 1" -		2.00	0.22	0.44
81065	23	Trim - Batten - 3.0mm x 7/8" x 96		0.00	0.00	0.00
8-8369	24	OUTSIDE SHOWER LOC		1.00	6.75	6.75

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
990	6	MISCELLANEOUS REPAIR		0.20	150.00	30.00
990	6	MISCELLANEOUS REPAIR		0.00	150.00	0.00
990	21	MISCELLANEOUS REPAIR		0.00	150.00	0.00
990	21	MISCELLANEOUS REPAIR		0.20	150.00	30.00
990	22	MISCELLANEOUS REPAIR		0.00	150.00	0.00
990	22	MISCELLANEOUS REPAIR		0.10	150.00	15.00

Claim : 66863

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      23  MISCELLANEOUS REPAIR      0.00     150.00      0.00
Z990      23  MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990      24  MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990       3  MISCELLANEOUS REPAIR      0.50     150.00     75.00
Z990       8  MISCELLANEOUS REPAIR      0.10     150.00     15.00
Z990      10  MISCELLANEOUS REPAIR      0.00     150.00      0.00
Z990      10  MISCELLANEOUS REPAIR      0.30     150.00     45.00
Z990      11  MISCELLANEOUS REPAIR      0.20     150.00     30.00
Z990      14  MISCELLANEOUS REPAIR      0.30     150.00     45.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT        8  UPS- SEAM TAPE AND DRAWER SLIDES      1.00     12.83     12.83

```

```

Parts Total:      384.32
Labour Total:     345.00
Sublet Total:       0.00
Extras Total:      12.83

```

```

>>>> Claim Total:      742.15

```

Customer Signature: _____

Date: _____