



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73573
Promised Date:
10 JUN 26



WO #: 73573

Customer Name: 61686 - BARRERA,
BOBBI L

Completed Date: 06 JUL 26

Invoice#:

Author: BRIAN

Stock Desc: 9608 2026 TRACER 235RK

Serial#: 5ZT2TRNB7TB526454

Chassis#: 5ZT2TRNB7TB526454

Miles/Hrs:

Tag#:

Purchased Date: 11 JUN 26

Warranty Date: 11 JUN 26

Date In: 18 JUN 26

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES KITCHEN SINK COVER CRACKED

CAUSE: DEFECTIVE COVER

CORRECTION: REMOVE AND REPLACE COVER

13 1/4 X 11 3/4

PART ONLY CLAIM

GAVE CUSTOMER COVER

Parts

Part #	Description	Qty	Price	Total
F100521445	BAMBOO SINK COVER - 11.75" X 13.25"	1.00	9.49	9.49

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	17.27	17.27

Subtotal for Job #1: 26.76

Parts Total: 9.49
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 17.27
WORK ORDER TOTAL: 26.76

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer #: 61686
BARRERA, BOBBI L



Customer Signature : _____

Date: 06 Jul 2026

W/O: 73573
Promised Date: 19 JUN 26



Customer #: 61686
BARRERA, BOBBIL



Customer Work
Order

