



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73041-1
Promised Date:
07 11 26



WO #: 73041-1

Customer Name: 1000 - MYERS "RV"
CENTER, INC.

Completed Date: 03 JUL 26

Invoice#:

Author: ADVISOR

Stock Desc: 9682 2026 AVENGER
25MKO

Serial#: 942177

Chassis#: 5ZT2AVPB0TB942177

Miles/Hrs:

Tag#:

Purchased Date:

Warranty Date:

Date In: 28 APR 26

Time In:

Job #01 - Warranty

COMPLAINT: underbelly hanging sdown under unit at the front

CAUSE: Pulled loose during transport

CORRECTION: Tucked in the wires and secured to prevent falling again, resecured the underbelly and made a repair using underbelly tape at the access panel just behind the a frame.

Job completed. Requesting .75

Labor

Job #	Description	Total
01	MULTIPLE LABOR CODES	142.50

Parts

Part #	Description	Qty	Price	Total
99-8106	BOARD REPAIR TAPE FOR UNDERBELLY - 1 FT	4.00	0.29	1.16

Subtotal for Job #01: 143.66

Job #02 - Warranty

COMPLAINT: Decals are bubbly and peeling

CAUSE: Decal

CORRECTION: Done

Labor

Job #	Description	Total
02	MULTIPLE LABOR CODES	237.50

Parts

Part #	Description	Qty	Price	Total
F100731387	GRAPHIC, SIDE LEGEND, AVENGER 2026 (171026)	1.00	7.83	7.83

Other Services

Code	Description	Qty	Price	Total
FRT	SHIPPING & HANDLING CHARGES	1.00	16.68	16.68

Subtotal for Job #02: 262.01

Customer #: 1000
MYERS "RV" CENTER,
INC.,





Job #03 - Warranty

COMPLAINT: Black tank handle missing

CAUSE: Replace handle

CORRECTION: Done

Labor

Job #	Description	Total
03	MULTIPLE LABOR CODES	5.70

Parts

Part #	Description	Qty	Price	Total
60P14615A	HANDLE, T1006-6N, BLACK, 19462	1.00	0.69	0.69

Subtotal for Job #03: 6.39

Job #04 - Warranty

COMPLAINT: Lino is bubbly in bathroom

CAUSE: Floor is bubbly due to floor separation

CORRECTION: Peel back the bathroom floor from base of shower and around toilet seal to expose said area. Once floor is peeled back will need to sand down edge of floor board where it is coming up and general area of floor to make flat again. Once floor is sanded and flat will need to re glue the Lino back into place and add corner trim around edges of floor to hide cut marks . Once floor is re glued and trim is installed will need to re install toilet and test for leaks .

Labor

Job #	Description	Total
04	MULTIPLE LABOR CODES	475.00

Subtotal for Job #04: 475.00

Job #05 - Warranty

COMPLAINT: Front awning arm needed to be adjusted slightly

CAUSE: Awning not closing properly

CORRECTION: Awning arm adjusted and tested job complete

Labor

Job #	Description	Total
05	MULTIPLE LABOR CODES	190.00

Subtotal for Job #05: 190.00

Job #06 - Warranty

COMPLAINT: Front bedroom doorway has bubbles in Lino

CAUSE: Bedroom door lino bubbling due to lack of floor glue

CORRECTION: Add more glue to said area to re adhere requesting .75

Labor

Job #	Description	Total
06	MULTIPLE LABOR CODES	142.50

Subtotal for Job #06: 142.50



W/O: 73041-1
Promised Date: 07 JUL 26

Parts Total:	9.68
Labour Total:	1,193.20
Sublet Total:	0.00
Extras Total:	16.68
WORK ORDER TOTAL:	1,219.56

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 03 Jul 2026

Customer #: 1000
MYERS "RV" CENTER,
INC.,

