



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27392



WO #: 27392

Customer: 90380 - BATES, CHARLES
Address: 171 ISLEY RD
BLOUNTVILLE, TN
37617

Home Phone: (423) 794-0085

Work Phone:

Author: CLP

Location: IH

Invoice #:

Stock #: 11139

Stock Desc: 2026 THFW FOREST RIVER ROGUE
351G2

Model: 351G2

Serial #: 4X4FVGL2XT5403602

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 03 OCT 25

Date In: 06 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 03 OCT 25

Job #1 - Warranty

COMPLAINT: CUS STATES THE CLEARANCE LIGHT COVER KEEPS FALLING OFF

CAUSE: TECH VERIFIED THERE IS A DEFECT IN THE CLEARANCE LIGHT HOUSING AND THE
LENSE WILL NOT STAY ON.

CORRECTION: REPLACE THE CLEARANCE LIGHT HOUSING AND LENSE AND RESEAL AROUND
LIGHT.

LABOR .30

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Warranty

COMPLAINT: CUS STATES THE LADDER BOTTOM PLUG IS MISSING

CAUSE: TECH VERIFIED THE LADDER DOES NOT HAVE A PLUG ON ONE OF THE BOTTOMS

CORRECTION: REPLACE PLUG ON BOTTOM OF LADDER

LABOR .05

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: REFER DISPLAY IS NOT SHOWING CHECK AND ADVISE

CAUSE: VERIFIED THE EXTERIOR DOOR PANEL ON FRIDGE THAT SHOWS THE NUMBERS IS NOT
WORKING. THERE IS NO DISPLAY LIGHTING UP AS DESIGNED TO DO SO.

CORRECTION: REPLACE THE LIGHT MONITOR PANEL

LABOR .40

Subtotal for Job #3: 0.00

Customer #: 90380
BATES, CHARLES



W/O: 27392

Parts Total:	0.00
Labour Total:	0.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Date: 16 Jul 2026

Customer Signature : _____

Customer Work
Order



Customer #: 90380
BATES, CHARLES

