



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27380



WO #: 27380

Customer: 93152 - CULBERTSON, ROBERT
Address: PO BOX 262
NORTON VA
24273
Home Phone: (276) 219-9555
Work Phone:
Author: S.DAVIS
Location: IH
Invoice #:

Stock #: 11126
Stock Desc: 2025 TT KZ-RV CONNECT SE
211MKSE
Model: 211MKSE
Serial #: 4EZTL2320S4046550
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim:

Purchase Date: 28 APR 26
Date In: 02 JUL 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date: 28 APR 26

Job #1 - Warranty

COMPLAINT: ON PREVIOUS CLAIM KZ0041437 WE REPLACED THE SMALL VIBRATION MOTORS AND THIS DID NOT FIX THE ISSUE COMPLETELY. THE CUP HOLDER LIGHT IS STAYING ON.

CAUSE: TECH STATED THE CUP HOLDER AND WIRING HARNESS IS FAULTY.

CORRECTION: REPLACE THE COMPLETE CUP HOLDER AND WIRING HARNESS TO IT.
LABOR .40

Subtotal for Job #1: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 93152
CULBERTSON, ROBERT



Customer Signature : _____

Date: 02 Jul 2026

