



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27236



WO #: 27236

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11315

Stock Desc: 2026 C FOREST RIVER FORESTER
3051SF

Model: 3051SF

Serial #: 1FDXE4FN9VDD01081

Chassis #: 1FDXE4FN9VDD01081

Mileage: 1000

Key #:

Req'n #:

License #:

Trim:

Purchase Date:

Date In: 01 JUN 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 30 JUN 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: LIGHT SPOT ON CABINET DOOR UNDER TABLE BENCH

CAUSE: NOTED ON DAF

CORRECTION: COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
1	COLOR BLEND	0.15	26.25
Subtotal for Job #1:			26.25

Job #2 - Warranty

COMPLAINT: CABINET DOOR ABOVE BENCH HAS A SMALL CHIP

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
2	FILL AND COLOR	0.15	26.25
Subtotal for Job #2:			26.25

Job #3 - Warranty

COMPLAINT: CABINET DOOR ABOVE THE ENTRY DOOR HAS A CHIP ON THE BOTTOM CORNER

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA

LABOR .20

Labor

Job #	Description	Hours	Total
3	COLOR AND FILLED	0.15	26.25

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Subtotal for Job #3: 26.25

Job #4 - Warranty

COMPLAINT: STILE NEXT TO FRIDGE IS SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: FILL, COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
4	COLOR AND FILLED	0.15	26.25

Subtotal for Job #4: 26.25

Job #5 - Warranty

COMPLAINT: CABINET OVER STOVE IS CHIPPED IN TWO PLACES

CAUSE: NOTED ON DAF

CORRECTION: FILL,COLOR AND BLEND AREA
LABOR .20**Labor**

Job #	Description	Hours	Total
5	FILL AND COLOR	0.15	26.25

Subtotal for Job #5: 26.25

Job #6 - Warranty

COMPLAINT: BLACK STAIN ON BOTTOM RIGHT WALL CORNER GOING INTO THE BEDROOM

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AREA AND COLOR BLEND
LABOR .20**Labor**

Job #	Description	Hours	Total
6	CLEAN AND COLOR	0.15	26.25

Subtotal for Job #6: 26.25

Job #7 - Warranty

COMPLAINT: WALL NEXT TO BATHROOM SINK LEFT OF MIRROR IS CUT AND PEELING

CAUSE: NOTED ON DAF

CORRECTION: FILL,SMOOTH, COLOR AND BLEND AREA
LABOR .30**Labor**

Job #	Description	Hours	Total
7	CLEAN AND COLOR	0.15	26.25

Subtotal for Job #7: 26.25

Job #8 - Warranty

COMPLAINT: BOTTOM DRAWER IN BEDROOM IS SHORTER THAN THE TOP 2

CAUSE: NOTED ON DAF

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CORRECTION: REPLACE THE BOTTOM DRAWER TO MATCH THE OTHER DRAWERS
LABOR .30

DENIED

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: CEILING HAS SEVERAL BROWN SPOTS AT ENTRY AND A PLACE WHERE THE WHITE COLOR IS PEELED BACK

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND AREA
LABOR .30

Labor

Job #	Description	Hours	Total
9	CLEANED AND COLOR	0.20	35.00

Subtotal for Job #9: 35.00

Job #10 - Warranty

COMPLAINT: UNIT WAS VERY DIRTY WITH DEBRIS ON THE FLOOR, EXTRA WIRING THAT HAD BEEN CUT AND LOTS OF WOOD CHIPS. THIS WAS MOSTLY ON THE SLIDE FLOOR AREA

CAUSE: NOTED ON DAF

CORRECTION: SWEEP,VACUUM EDGES AND CORNERS TO REMOVE DEBRIS TO NOT DAMAGE THE FLOORING
LABOR .50

DENIED

Subtotal for Job #10: 0.00

Parts Total: 0.00
Labour Total: 218.75
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 218.75

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 30 Jun 2026

W/O: 27236



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

