



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27329



WO #: 27329 (Appointment Date: 17 JUN 2026 - Time: 10:00am)

Customer: 93440 - SWIFT, COURTNEY
Address: 305 PLEasant HILL RD
CHUCKEY, TN
37641

Home Phone: (423) 426-3276

Work Phone:
Author: THAYES

Location: IH

Invoice #:

Stock #:
Stock Desc: 2025 TT KEYSTONE
Model:
Serial #: 4YDTRNG11SD460002
Chassis #:
Mileage:
Key #:
Req'n #:
License #:
Trim: 15RB

Purchase Date:
Date In: 17 JUN 26
Promise Date:
Promise Time:
Schedule Date:
Completed:
Warr. Date:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES HALF THE LIGHTS ARE NOT WORKING IN HALF THE CAMPER -
PLEASE CHECK AND ADVISE

CAUSE: CEILING LIGHTS IN LIVING AREA, KITCHEN AND HOOD FAN ARE INOP. FOUND A 15 AMP
FUSE BLOWN, REPLACED IT AND IT BLEW IMMEDIATELY. REMOVE SWITCH PANEL TO GAIN
ACCESS TO BACK SIDE OF FUSE BOX, INSPECTED WIRING AND LOOKS GOOD. USING METER
VERIFIED SHORT TO GROUND AND LIGHTING CIRCUIT. TECH REMOVED LOADS 1 AT A TIME
WHILE TESTING TO GROUND CIRCUIT IS STILL GROUNDED WITH ALL LOADS REMOVED AND
SWITCH REMOVED FROM CIRCUIT. THIS INDICATES A SHORT IN WIRING THROUGH WALL AND
UNDERBELLY USING ALTERNATE 12 VDC SOURCE. TESTED LIGHTS ON ALTERNATE
SOURCE ARE WORKING.

CORRECTION: WILL NEED TO RUN A NEW 12 VDC SUPPLY FROM FUSE PANEL TO SWITCH PANEL
IN ORDER TO PROPERLY CORRECT CONCERN.
LABOR 4.0

Subtotal for Job #1: 0.00

Job #2 - External

DEWIN

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #2: 0.00

Job #ROOFINS - External

COMPLAINT: COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____
CHECK SKYLIGHTS _____
CHECK ROOF VENTS _____
CHECK LUBE & ANTENNA _____
CHECK SATELLITE _____
CHECK RUBBER _____

CAUSE: SEALS ARE OPEN AND NOT IN GOOD SHAPE. THERE IS A LOT OF PLACES THAT WILL
ALLOW WATER AND MOISTURE IN.

CORRECTION: SEALANT AROUND COMPONENTS AND FRONT CAP NEED TO BE STRIPPED, AREA
CLEANED AND NEW SEALANT LAID DOWN TO CORRECT THE ISSUES
LABOR 4.0

Customer #: 93440
SWIFT, COURTNEY



Subtotal for Job #ROOFINS: 0.00

W/O: 27329

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 26 Jun 2026



Customer #: 93440
SWIFT, COURTNEY

