

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA Labor rate: \$150.00 OWNER INFORMATION	CLAIM STATUS Authorized CLAIM 985385 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAXB2MX021702 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 205 / 205 ITEM # ACAT323BHDCKLE DEALER RO # 66929 CLAIM START DATE 04/01/2022 CLAIM END DATE 01/01/1900
--	---

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code SB-456-09-00-004005	Operational Description 205-1314 - EXTERIOR SCREWS MISSING SEALANT - Technical Service Bulletin/Sealant/Perform/No Tread Code								
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-01 15:12:02 :: RECALL FOR THE DIAMOND PLATE removed screws as recommended by recall and put silicone on and around screws, tightened screws										
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 20%;">0.10</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 20%;">\$15.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.10</td> <td>Appr Labor Amt</td> <td>\$15.00</td> </tr> </table>	Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00	Appr Hrs	0.10	Appr Labor Amt	\$15.00
Dlr Sub Hrs	0.10	Sub Labor Amt	\$15.00							
Appr Hrs	0.10	Appr Labor Amt	\$15.00							

Notes

Labor

Line# 2	Operation Code 20-55-01-11-000850	Operational Description Awning LED Light Strip - Exterior/Awnings - Electrical (Carefree of Colorado)/Replace/Electrical								
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-01 15:14:20 :: CUSTOMER STATES THAT WHEN THE BLUE LIGHTS ARE ON UNDER THE AWNING, SOME OF THE LIGHTS ARE GREEN has 16 ft of lights,found 5-6 lights that are green and 3 that dont light INSTALL NEW LIGHT										
	Model # NA Serial # NA	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 20%;">0.50</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 20%;">\$75.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.50</td> <td>Appr Labor Amt</td> <td>\$75.00</td> </tr> </table>	Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00	Appr Hrs	0.50	Appr Labor Amt	\$75.00
Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00							
Appr Hrs	0.50	Appr Labor Amt	\$75.00							

Notes

Labor

Line# 3	Operation Code 60-136-15-00-001499	Operational Description Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code								
Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-04-01 15:16:15 :: CUSTOMER ADVISED THAT THE WOOD IN THE OUTDOOR KITCHEN WAS DAMAGED AS A RESULT OF THE OUTDOOR KITCHEN SINK LEAKING FOUND LEAK AND DAMAGED WOOD REPAIR LEAK AND NOW NEED TO REPLACE THE WOOD										
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 20%;">3.00</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 20%;">\$450.00</td> </tr> <tr> <td>Appr Hrs</td> <td>2.50</td> <td>Appr Labor Amt</td> <td>\$375.00</td> </tr> </table>	Dlr Sub Hrs	3.00	Sub Labor Amt	\$450.00	Appr Hrs	2.50	Appr Labor Amt	\$375.00
Dlr Sub Hrs	3.00	Sub Labor Amt	\$450.00							
Appr Hrs	2.50	Appr Labor Amt	\$375.00							

Notes

EXCESSIVE AMOUNT REQUESTED.

Submitted Labor Amt \$540.00 Parts & Freight \$0.00	Approved Labor Amt \$465.00 Parts & Freight \$0.00
--	---

Total \$540.00

Total \$465.00

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.