



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27253
Promised Date:



WO #: 27253

Customer: 53089 - GILES, STANLEY
Address: 300 WALNUT GROVE ROAD
GREENEVILLE, TN
37743

Home Phone: 423-588-8997

Work Phone:

Author: SPD

Location: IH

Invoice #:

Stock #: 11006

Stock Desc: 2025 CT FOREST RIVER

ROCKWOOD CAMP 1910FT

Model: 1910FT

Serial #: 4X4CFM71XSD320868

Chassis #:

Mileage: 0

Key #: 1775

Req'n #: 62834

License #:

Trim:

Purchase Date: 27 MAY 26

Date In: 03 JUN 26

Promise Date: 30 JUL 26

Promise Time: 09:00am

Schedule Date:

Completed: 03 JUL 26

Warr. Date: 27 MAY 26

Job #1 - Warranty

COMPLAINT: CS THAT A BUMP STOP HAS COME LOOSE FROM THE END OF THE BED RAIL

CAUSE: BED END CAP CAME OFF AND THIS ALLOWS THAT SIDE TO COME COMPLETELY OUT OF UNIT.

CORRECTION: REPLACE THE END CAP AND SECURE CORRECTLY IN PLACE

LABOR .50

Labor

Job #	Description	Hours	Total
1	REPLACED	0.50	87.50

Parts

Part #	Description	Qty	Price	Total
F100489285	BED SLIDE PART - 3E-3: ROUNDED END CAP W/ RIVOT - BLACK - V# ROUND END CAP & RIVET	1.00	1.08	1.08

Other Services

Code	Description	Qty	Price	Total
SHP	SHIPPING/FREIGHT FEE	1.00	25.45	25.45

Subtotal for Job #1: 114.03

Job #2 - Warranty

CS THAT THE STORAGE COMPARTMENTS ARE HARD TO UNLOCK AND LOCK

Subtotal for Job #2: 0.00

Job #3 - Warranty

CS THAT THE CABLES THAT FO TO THE FRONT LIFTING LEGS HAVE BROKE

Subtotal for Job #3: 0.00

Job #4 - Warranty

CS THAT THERE IS A FLAP THAT HOLD WATER AND IT WILL NOT DRAIN OFF FROM THE UNIT

Customer #: 53089
GILES, STANLEY



W/O: 27253
Promised Date: 30 JUL 26

Subtotal for Job #4: 0.00

Parts Total: 1.08
Labour Total: 87.50
Sublet Total: 0.00
Extras Total: 25.45

WORK ORDER TOTAL: 114.03

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 03 Jul 2026

Customer #: 53089
GILES, STANLEY

