



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 6694  
Promise Date: 30 APR 22

### CUSTOMER WORK ORDER

WO #: 66934

Customer: 50572 - Russler, Baylee B. -  
812-204-2452

Tag:

Author: BJW

Location: 0513 LET BB KNOW THAT  
PARTS ARE HERE

Stock #: 10710

Stock Desc: 2021 TT KEYSTONE  
SPRINGDALE 280BH

Chassis #: 4YDT28029M3104978

Serial #: 4YDT28029M3104978

Mileage: 0

Licence:

Invoice #: 376852

Date In: 29 MAR 22

Promise: 30 APR 22

Date Sched:

Completed: 13 MAY 22

Warr. Date: 17 OCT 20

#### Job #1 - Warranty

COMPLAINT: Transferred to BAS\*67284 on 29 APR 22

Estimate amount was 0.00

THE SIDING IS COMING DETACHED FROM THE OFF DOOR FRONT SIDE NEAR THE TOP. UNIT IS  
IN STORAGE LOCATION 82

CORRECTION: REMOVE BLIND. REMOVE WINDOW. REMOVE FRONT TRIM AND REMOVE REAR  
TRIM. REMOVE SEALS ON BOTH SIDES OF THE SLIDEROOM. REMOVE UPPER SEAL ON  
SLIDEROOM. REMOVE INSIDE TRIM AND SLIDEROOM STOPS TO DROP ROOM OUT TO REMOVE  
METAL TRIM ON ALL SIDES OF SLIDEROOM THAT HOLDS THE SEALS. REMOVE DAMAGED SIDING.  
CUT AND INSTALL NEW SIDING. PUT BACK REAR AND FRONT TRIM. PUT BACK SEALS AND METAL  
THAT HOLDS THEM. PUT BACK INSIDE TRIM AND PUTTY HOILES. SILICONE ALL AREAS THAT ARE  
NEEDED

#### Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

#### Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECALS	0.00	12.54	0.00
FRT	FREIGHT/CRATE METAL	0.00	844.75	0.00

**Subtotal for Job #1: 0.00**

#### Job #2 - External

COMPLAINT: CUSTOMER'S DOG CHEWED THE CORNER TRIM BETWEEN THE ENTRANCE DOOR  
AND THE ENTERTAINMENT CENTER. UNIT IS IN STORAGE LOCATION 82

CORRECTION: PARTS ORDERED ON 4/4/22 REMOVED CORNER AND INSTALLED A NEW ONE

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C

Customer #: 50572  
Russler, Baylee B.





**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
<b>Subtotal for Job #2:</b>				<b>0.00</b>

**Job #3 - Warranty**

COMPLAINT: THE TRIM FROM THE REAR SIDE CEILING OF THE SLIDE ROOM FELL DOWN. UNIT IS IN STORAGE LOCATION 82

CORRECTION: REMOVED NAILS AND STAPLED BACK TRIM AND FILLED HOLES WITH PUTTY. TOOK PIC

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	30.00
<b>Subtotal for Job #3:</b>			<b>30.00</b>

**Job #4 - Warranty**

COMPLAINT: SOME OF THE STAPLES ARE COMING OUT OF THE PANELING IN THE BEDROOM. UNIT IS IN STORAGE LOCATION 82

CORRECTION: REMOVED WALL TAPE AND STAPLED BACK PANELS. TOOK PICS. ORDERED WALL TAPE. 4/4/22

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	0.00
Z990	MISCELLANEOUS REPAIR	BB	45.00
Z990	MISCELLANEOUS REPAIR	BB	0.00

**Parts**

Part #	Description	Qty	Price	Total
663144	Trim - OSC - 3/4" x 3/4" x 96" - FJP - Large - Jurupa Shadow - #201	1.00	14.97	14.97
6447	Seam - Tape - 1" -	25.00	0.18	4.50

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS-TRIM	1.00	37.02	37.02
FRT	UPS-SEAM TAPE	1.00	12.54	12.54
FRT	UPS-SEAM TAPE 5-5-22	1.00	11.76	11.76
<b>Subtotal for Job #4:</b>				<b>125.79</b>

**Job #5 - Warranty**

COMPLAINT: SOME OF THE PANELING ON THE STORAGE ABOVE THE BED IS LOOSE. UNIT IS IN STORAGE LOCATION 82

CORRECTION: STAPLED BACK TRIM ABOVE BED AND PUTTY HOLES

**Labor**

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	BB	15.00
<b>Subtotal for Job #5:</b>			<b>15.00</b>

**Job #6 - Internal**

COMPLAINT: INSTALL TOUNGE JACK TECH DAMAGED

CORRECTION: CUT OFF DAMAGED JACK AND INSTALL A JACK DENNY HAD

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	N/C



Subtotal for Job #6: 0.00

Parts Total: 19.47  
Labour Total: 90.00  
Sublet Total: 0.00  
Extras Total: 61.32

**WORK ORDER TOTAL: 170.79**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 13 May 2022

Customer Signature : \_\_\_\_\_

W/O: 6-44  
Promi  
Date: 30 APR 22



Customer #: 50572  
Russler, Baylee B.

