



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

Estimate: 27342 ROARK, RONNIE



Estimate: 27342 (Appointment Date: 24 JUN 2026 - Time: 09:00am)

Customer: 64452 - ROARK, RONNIE
Address: 137 HUGH GARLAND RD

37659
Home Phone: 423-930-7721
Work Phone:
Author: CLP
Location: IH
Invoice #:

Stock #:
Stock Desc: 2019 GRAND DESIGN REFLECTION
Model:
Serial #: 573FR3623L3325568
Chassis #:
Mileage:
Key #:
Req'n #: 62820
License #:
Trim: 298BH

Purchase Date:
Date In: 22 JUN 26
Promise Date:
Promise Time: 12:00am
Schedule Date:
Completed:
Warr. Date:

Job #1 - External

CUSTOMER STATES FRIDGE IS NOT COOLING ENOUGH, STAYS AT 37-41 DEGREES - PLEASE CHECK AND ADVISE

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - External

REQUEST BEARING PACK, AND BREAK CHECK - APPROVED ALREADY

Parts

Part #	Description	Qty	Price	Total
010-036-00	OIL SEAL-DOUBLE LIP	0	13.99	0.00

Subtotal for Job #2: 0.00

Job #3 - External

CUSTOMER STATES THE FAN (SHE THINKS IN FRIDGE) MAKING FUNNY NOISE - NOT CONSTANT - PLEASE CHECK AND ADVISE

Subtotal for Job #3: 0.00

Job #4 - External

CUSTOMER STATES SHE WOULD LIKE TO HAVE METAL CHROME MATCHING SHOWER FAUCET AND BATHROOM SINK FAUCET REPLACED,. PLEASE CHECK AND ADVISE. BATHROOM SINK FAUCET IS BY BATHROOM SINK IN BOX, SHOWER MATCHED TO THIS, APPROVED FOR .5 HR TO INSTALL SINK FAUCET

Subtotal for Job #4: 0.00

Job #5 - External

CUSTOMER REQUESTING TO GET PRICES FOR FOR BROWN VERTICAL BLINDS BETWEEN MICROWAVE AND STOVE - CHECK AND ADVISE



Subtotal for Job #5: 0.00

Job #ROOFINS - External

COMPLEMENTARY ROOF INSPECTION

CHECK CAULKING _____

CHECK SKYLIGHTS _____

CHECK ROOF VENTS _____

CHECK LUBE & ANTENNA _____

CHECK SATELLITE _____

CHECK RUBBER _____

Subtotal for Job #ROOFINS: 0.00

Job #7 - External

CUSTOMER STATES FAR BACK AWNING ON FRONT OF CAMPER IS STICKING, THEY CAN PULL IT MANUALLY, AND THEN IT WILL WORK, PLEASE CHECK AND ADVISE

Subtotal for Job #7: 0.00

Job #8 - External

CUSTOMER STATES THE BATHROOM CEILING FAN VENT IS LOOSE, PLEASE CHECK AND ADVISE

Subtotal for Job #8: 0.00

Job #9 - External

REQUESTING PRICE FOR SNAP PADS

Subtotal for Job #9: 0.00

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

Tax Total: 0.00

Estimate Total: 0.00

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 10 Jul 2026

