



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73707-1
Promised Date:
4 4 11 11 26

73707-1

WO #: 73707-1

Customer Name: 61900 - PETTY III,
ANDREW HOWARD

Completed Date:

Invoice#:

Author: BRIAN

Stock Desc: 9509 2025 TRACER 170RS

Serial#: 5ZT2TRFC7SB526069

Chassis#: 5ZT2TRFC7SB526069

Miles/Hrs:

Tag#:

Purchased Date: 10 JUL 26

Warranty Date: 14 JUL 26

Date In: 14 JUL 26

Time In:

Job #01 - Warranty

COMPLAINT: WARRANTY ITEM solar controller

CAUSE: THERE WAS NO CONNECTION TO THE BATTERY FROM THE SOLAR CONTROLLER, THE EYELEY O THE CABLE ABOVE THE UNDERBELLY WAS INSUFFICIENTLY CRIMPED AND THE WIRE HAD NO SLACK, SO THE WIRE PULLED FROM THE CONNECTOR.

CORRECTION: Started by seting voltage from the solar panels to the controller, voltage was good, tested battery voltage at the controller and no voltage, i unscrewed the battery disconnect for the solar, tested voltage behind there, still no voltage. the wires run down into the underbelly, i removed an access cover underneath, but no access hole, had to cut a hole to access the breakers install above, found the wire pulled from connector, nhad to extend the 8ga wires bc of the lack of slack during insatallation. removed and installed a new eyelet, tested the system, its now charging as it should, had to reinstall the battery disconnect and the underbelloy access cover. job completed. requesting 1.5

Labor

Job #	Description	Total
01	MISC LABOUR CODE (WARRANTY)	N/C
Subtotal for Job #01:		0.00

Job #02 - Warranty

COMPLAINT: WARRANTY ITEM furnace not working

CAUSE: The heater would not kick on..

CORRECTION: Began diagnosis at the interior controls by checking thermostat operation and confirming the furnace was being commanded on. Inspected thermostat settings and monitored system response while verifying proper operation of the control circuit. After confirming the concern persisted, moved to the exterior furnace compartment for further diagnosis. Inspected wiring, control board, fuse, and electrical connections while tracing the call-for-heat circuit. During inspection, discovered the furnace's dual/service switch had become unplugged, preventing the furnace from operating. Reconnected the switch, secured the connection, and retested the furnace. Furnace ignited and operated normally with proper heat output. Total diagnostic time approximately 0.75 labor hours (45 minutes).

Labor

Job #	Description	Total
02	MISC LABOUR CODE (WARRANTY)	N/C

Customer #: 61900
PETTY III, ANDREW
HOWARD

61900

W/O: 73707-1
Promised Date: 14 JUL 26

73707-1

Customer #: 61900
PETTY III, ANDREW
HOWARD

61900

Subtotal for Job #02: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 0.00

NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Date: 15 Jul 2026

Customer Signature : _____