



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67074

CUSTOMER WORK ORDER

WO #: 67074

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0420 CHECK WORK

Stock #: 11084
Stock Desc: 2022 5W FOREST RIVER
SABRE 37FLH
Chassis #: 5ZT3SR2B3N6110618
Serial #: 5ZT3SR2B3N6110618
Mileage: 0
Licence:

Invoice #:
Date In: 11 APR 22
Promised:
Date Sched:
Completed: 14 APR 22
Warr. Date:

Job #RECALL - Warranty

COMPLAINT: 22V135THE LUGS ON THE SHORE CORD COULD BE LOOSE CHECK AND ADVISE

CAUSE: removed inlet. removed wires and inspected. wires and insulation look good. lugs were very loose.

CORRECTION: tightened lugs to spec. installed inlet. sealed with silicone.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.50

Subtotal for Job #RECALL: 37.50

Parts Total: 0.00
Labour Total: 37.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 37.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 14 Apr 2022

Customer #: 1000
BASDEN'S AMERICAN RV,

