

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67127
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 39027 - EDDY WALTER
Address: 939 N PEERLESS RD EVANSVILLE, IN

47712

Phone: 812-589-4633

Stock Number: 11031 - 2021 MONTANA 3231CK 4YDF32321M4704827

VIN: 4YDF32321M4704827 HIN: SER#: 4YDF32321M4704827

Mileage: 0 Work Order Comp: 11 MAY 22

Auth. No: Dealer #: 1194

Warr. Date: 28 AUG 21

Work Order Date: 18 APR 22 Inv #: 376729

WO # Job # Description JOB INFORMATION

67127 1 THERE IS WHITE AND CROME MOLDING THAT HAS PULLED LOOSE
THERE IS WHITE AND CHROME MOLDING THAT HAS PULLED LOOSE.
Checked for white and chrome molding. Found it on shower pan
across bottom. Loose in the middle. Has sawdust on mounting
surface. Moulding needs replaced.. 4/21/2022: Turned in parts
request for a new part. 5/3/2022: Rec'd new part. Moved unit
back into shop from service lot. Pulled off old chrome trim.
Cleaned mounting surface. Applied stickon new chrome trim across
bottom of shower stall. Sealed ends with white silicone.
Returned unit to service lot.

67127 9 BLACK TANK FLUSH LEAKS IN THE BATHRRROM
BLACK TANK FLUSH LEAKS IN BATHROOM.
Connected black tank flusher to water. Water pouring out of top
of check valve. Removed flusher check valve. Found a stink bug
inside valve. Installed new black tank check valve. Checked
connections for leaks. None found.

67127 3 BATHROOM SCREEN HAS SILICONE ON IT SEE WHAT WE CAN DO
BATHROOM SCREEN HAS SILICONE ON IT. SEE WHAT WE CAN DO.
Removed screen from bathroom window. Tried to clean silicone
from screem material. Silicone would not come off without
damaging screen material. Removed screen from frame. Installed
new screen material in frame. Rewmounted screen in bathroom
window.

Claim : 67127

 WO # Job # Description JOB INFORMATION

 Part No Job# Description PARTS Qty Price Total

 325708 1 Trim - Body Moldin 5.00 2.45 12.25
 282770 9 94239 VACUUM BREAK 1.00 21.72 21.72

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISCELLANEOUS REPAIR 0.20 150.00 30.00
 Z990 1 MISCELLANEOUS REPAIR 0.00 150.00 0.00
 Z990 9 MISCELLANEOUS REPAIR 0.30 150.00 45.00
 Z990 3 MISCELLANEOUS REPAIR 0.30 150.00 45.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 1 UPS-MOLDING 1.00 13.48 13.48
 SS 9 SHOP SUPPLIES 1.00 0.00 0.00

Parts Total: 33.97
 Labour Total: 120.00
 Sublet Total: 0.00
 Extras Total: 13.48

>>>> Claim Total: 167.45

Customer Signature: _____

Date: _____