



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67145

CUSTOMER WORK ORDER

WO #: 67145

Customer: 1000 - BASDEN'S AMERICAN

RV -

Tag:

Author: BH

Location: 0430 CHECK WORK

Stock #: 11186

Stock Desc: 2022 5W ALLIANCE RV

VALOR 41V15

Chassis #: 7M5FV4432NA006354

Serial #: 7M5FV4432NA006354

Mileage: 0

Licence:

Invoice #:

Date In: 20 APR 22

Promised:

Date Sched:

Completed: 30 APR 22

Warr. Date:

Job #PDINFW - Internal

COMPLAINT: PDI - NEW FIFTH WHEEL

CORRECTION: PDI, FIND UNIT CLOSE UP AND BRING IN, FILL LP TANKS (2 TANKS AT 30 lbs)
CHECK LIGHTS, NO 12 POWER LINE ON 7 WAY, OPEN BOX AND FOUND NOT CONNETED FIX,
CHECL LIGHTS BRAKES, ROOF, FILL FRESH TANK, CHECK WATER SYSTEMS FILL AND DRAIN ALL
TANKS, #1 GRAY TANK NOT READING ON PANEL (4), FIXED PROBLEM, CHECK ELETRIC SYSTEM
NO POWER IN UNIT FROM SHORE LINE, FOUND HIDEN SWITCH ON INVERTER TURNED ON
SWITCH FIXED PROBLEM, WATER HEATER WILL NOT WORK ON ELETRIC, FIXED PROBLEM
CHECL LP SYSTEM RUN LP DROP TEST, TACK DOWN SHADE AND TURN IN PO,

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	JP	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	12.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: THE WATER HEATER IS NOT FUNCTIONING ON 120V.

CORRECTION: REMOVE T STAT COVER ON SUBURBAN WATER HEATER AND CHECK FOR 120 vac,
NO POWER FOUND, FIND BREAKER PANEL AND REMOVE COVER CHECK BREAKERS, FOUND
FEAD WIRE FROM BREAKER NOT CONETED, CONNECT UP WIRE AND TEST FOR POWER AT
WATER HEATER T STAT, PUT COVERS BAK ON

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	105.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 105.00

Job #2 - Warranty

COMPLAINT: THE HAPPY JACK BED IN THE GARAGE IS NOT RAISING HIGH ENOUGH ON ONE SIDE TO LOCK INTO PLACE.

CAUSE: HAPPY JACK BED WAS MISS TIMED AT THE FACTORY,

CORRECTION: WORK BEDS AHD RETIME MOVING 1 POINT AT A TIME TO GET IN TIMMING, USEING LCI HAPPY JACK INSUTIONS

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	75.00

Subtotal for Job #2: 75.00

Job #3 - Warranty

COMPLAINT: THE SHADE OVER THE SOFA DOES NOT RAISE.

CORRECTION: TACK DOWN GET #S AND TURN IN A PO

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00

Parts

Part #	Description	Qty	Price	Total
13494	Shade - Night - 50	1.00	90.99	90.99

Subtotal for Job #3: 120.99

Job #4 - Warranty

COMPLAINT: GREY TANK #1 NOT READING ON MONITOR

CORRECTION: trace water drains, check wire on back of control panel, cut underbelly and check wires found ground wire loose for #1 gray tank, found shower and front washer drain in to gray #1, bathroom sink and kitchen sink drain in to gray #2, repair wires and test

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	36.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	162.00

Subtotal for Job #4: 198.00

Parts Total:	90.99
Labour Total:	408.00
Sublet Total:	0.00
Extras Total:	0.00

WORK ORDER TOTAL: 498.99

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer #: 1000
BASDEN'S AMERICAN RV,

Customer Signature : _____

Date: 03 May 2022

W/O: 67145



Customer #: 1000
BASDEN'S AMERICAN RV,



Customer Work
Order

