



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27525



WO #: 27525

Customer: 70970 - BROWN, WILLIAM
Address: 751 GEORGE MALONE ROAD
GREENEVILLE, TN
37745

Home Phone: (423) 552-7484

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11231

Stock Desc: 2026 DT FOREST RIVER SANDPIPER
389HBFL

Model: 389HBFL

Serial #: 4X4TSAR2XTJ048759

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 13 JUL 26

Date In: 03 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 13 JUL 26

Job #1 - Warranty

COMPLAINT: CUST COMPLAINED THE ICE MAKER IN THE FREEZER WILL NOT MAKE ICE.

CAUSE: CHECKED FOR WATER TO THE ICE MAKER AND VOLTAGE ALL IS GOOD. RESET THE BOARD AND APPLIED A CUP OF WATER TO ACTIVATE THE MOLD. THIS WAS FRIDAY, CUST CALLED AND STATED THE ICE MAKER DID NOT MAKE ITS OWN ICE OVER THE WEEKEND.

CORRECTION: REPLACE THE ICE MAKER
LABOR .20

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THE SLIDING DOOR IS SHOWING LIGHT AT THE TOP AND THE DOOR IS NOT CLOSING ALL THE WAY

CAUSE: VERIFIED THE SLIDING DOOR IS LEAVING A GAP AND LIGHT IS COMING THROUGH AT THE TOP. ALSO FOUND THE FRAME IS NOT SECURED CORRECTLY ALLOWING FRAME TO FLEX WHEN OPENING DOOR.

CORRECTION: RESECURE FRAME AND ADJUST SLIDING DOOR
LABOR .30

Subtotal for Job #2: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer #: 70970
BROWN, WILLIAM



Customer Signature : _____

Date: 03 Aug 2026

W/O: 27525

Customer Work
Order



Customer #: 70970
BROWN, WILLIAM

