



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

WO #: 27456

Customer: 47602 - TRI-AM RV CENTER-EAST TN
Address: 1202 IDELL ROAD
BULLS GAP, TN
37711

Home Phone: 423-235-1167

Work Phone:

Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11336

Stock Desc: 2027 THTT FOREST RIVER ROGUE
32L132

Model: 32L132

Serial #: 4X4TVGH25V5404378

Chassis #:

Mileage: 0

Key #:

Req'n #: 62977

License #:

Trim:

Purchase Date:

Date In: 16 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed: 25 AUG 26

Warr. Date:

Job #1 - Warranty

COMPLAINT: OUTSIDE WATER HEATER DOOR WILL NOT STAY SHUT. THIS WAS TAPED WHEN THE UNIT ARRIVED AT DEALER.

CAUSE: NOTED ON DAF

FAULTY WATER HEATER DOOR LATCH

CORRECTION: REPLACE WATER HEATER DOOR LATCH AND TEST
LABOR .30

Labor

Job #	Description	Hours	Total
1	REPLACED WATER HEATER LATCH	0.30	52.50

Parts

Part #	Description	Qty	Price	Total
F100485333	WATER HEATER DOOR	1.00	21.42	21.42

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	12.50	12.50

Subtotal for Job #1: 86.42

Job #2 - Warranty

COMPLAINT: THE 1/2 BATH DOOR IS SCRATCHED

CAUSE: NOTED ON DAF

SCRATCHED AT FACTORY

CORRECTION: FILL, SMOOTH AND COLOR BLEND ALL SCRATCHED AREAS ON DOOR
LABOR .40

Labor

Job #	Description	Hours	Total
2	FILL AND COLOR	0.20	35.00

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	5.99	5.99

Subtotal for Job #2: 40.99

W/O: 27456



Customer #: 47602
TRI-AM RV CENTER-EAST
TN,



Job #3 - Warranty

COMPLAINT: GLASS DOOR FRAME/CASING IN KITCHEN AREA SCRATCHED IN SEVERAL PLACES ACROSS TOP.

CAUSE: NOTED ON DAF

CORRECTION: CLEAN AND COLOR BLEND THESE AREAS

LABOR .50

REQUESTING THE AMOUNT OF LABOR DUE TO THE TYPE OF MATERIAL AND PAINT THAT NEEDS TO BE MATCHED

Labor

Job #	Description	Hours	Total
3	PAINT MATCHED AND CLEANED AREA	0.50	87.50

Subtotal for Job #3: 87.50

Job #4 - Warranty

COMPLAINT: GLASS DOOR FRAME/CASING IN KITCHEN AREA SCRATCHED IN SEVERAL PLACES ACROSS TOP

CAUSE: NOTED ON DAF

CORRECTION: SMOOTH AREA, CLEAN AND COLOR BLEND

LABOR .50

REQUESTING THE AMOUNT OF LABOR DUE TO THE TYPE OF MATERIAL AND PAINT THAT NEEDS TO BE MATCHED.

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: DRAWER GUIDE FOR STOVE DRAWER IS ONLY LOCKING ON RIGHT SIDE/DRAWER COMES OPEN

CAUSE: NOTED ON DAF

CORRECTION: REMOVE DRAWER AND GUIDE TO ADJUST GUIDE TO FIT AND OPERATE

CORRECTLY AND REINSTALL

LABOR .40

Labor

Job #	Description	Hours	Total
5	ADJUSTED GUIDE	0.20	35.00

Subtotal for Job #5: 35.00

Job #6 - Warranty

COMPLAINT: MASTER BATHROOM DOOR IS CHIPPED AT TOP

CAUSE: NOTED ON DAF

CORRECTION: REPLACE DOOR

LABOR .40

Labor

Job #	Description	Hours	Total
6	REPAIRED DOOR	0.10	17.50

Subtotal for Job #6: 17.50

Job #7 - Warranty

COMPLAINT: BEDROOM CABINET DOOR HAS A BLACK STAIN ON IT

CAUSE: NOTED ON DAF

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,

CORRECTION: AREA NEEDS TO BE COLOR BLENDED TO MATCH THE CABINET
LABOR .20

Labor			
Job #	Description	Hours	Total
7	COLORED BLENDED	0.30	52.50
Subtotal for Job #7:			52.50

Job #8 - Warranty

COMPLAINT: MASTER BATH DOOR CASING GOING INTO BEDROOM SCRATCHED

CAUSE: NOTED ON DAF

CORRECTION: REMOVE DAMAGED CASING AND REPLACE WITH NEW
LABOR .75

Labor			
Job #	Description	Hours	Total
8	REPLACED DOOR CASING	0.20	35.00

Parts				
Part #	Description	Qty	Price	Total
30178736A	INTERIOR MOLDING U CHANNEL 2 7/8 X 8 BLACK	1.00	4.25	4.25

Other Services				
Code	Description	Qty	Price	Total
FRT	FREIGHT ON PARTS	1.00	151.92	151.92
Subtotal for Job #8:				191.17

Job #9 - Warranty

COMPLAINT: ON REAR GARAGE DOOR THE TOP LEFT BRACKET CAME OFF THE UNIT DURING
THE DAF IN SPECTION

CAUSE: NOTED ON DAF

CORRECTION: RESECURE BRACKET BACK INTO PLACE CORRECTLY
LABOR .30

Labor			
Job #	Description	Hours	Total
9	RESECURED BRACKET BACK INTO PLACE	0.30	52.50
Subtotal for Job #9:			52.50

Parts Total:	25.67
Labour Total:	367.50
Sublet Total:	0.00
Extras Total:	170.41
WORK ORDER TOTAL:	563.58

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 25 Aug 2026

Customer #: 47602
TRI-AM RV CENTER-EAST
TN,