

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA Labor rate: \$150.00 OWNER INFORMATION EDWARD M AMES 939 N PEERLES RD Evansville, IN 47712 USA Retail Date of Purchase 11/12/2021	CLAIM STATUS Authorized CLAIM 1023420 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAHC6NK003063 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 203 / 203 ITEM # BCAT192FQS DEALER RO # 67248 CLAIM START DATE 04/29/2022 CLAIM END DATE 01/01/1900 WARRANTY EXPIRATION DATE 11/12/2022
---	--

Claim Line Details

Labor

Line# 1	Operation Code 10-12-01-00-000262	Operational Description Slide Out Box - Frame & Chassis/Slide Out System - Lippert/Replace/No Tread Code
----------------	---	--

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-04-29 10:05:39 :: BEN TALKED TO ROBERT HE APPROVED 12 HRS THE BULB SEAL ON THE TOP OUTSIDE REAR IS STARTING TO COME OFF AND DOES NOT LOOK RIGHT BOTH INSIDE BULB SEALS AND TRACKS THAT THE SEALS GO ONTO ARE PULLED UP OVER THE TOP OF THE SLIDE ROOM AROUND THE MOTORS, OUTSIDE WIPER SEAL ON TOP OF SLIDE ISNT MOVING AND IS BUNCHED UP BECAUSE THE SLIDE ROOM IS TOO CLOSE TO THE TOP OF THE WALL. BULB SEAL ON OUTSIDE FRONT OF SLIDE ROOM IS ALSO DAMAGED. PULL ROOM OUT, REPLACE BAD AND TORN SEALS, CUT ROOM TALLER TO MAKE IT FIT. INSTALL IT AL LBACK Additional Note : bhoffman@americanrvcenter.com, 2022-04-29 10:08:27 :: IF I RUN IN TO PROBLEMS I WILL GIVE ROBERT A CALL

Model #	Dir Sub Hrs	12.00	Sub Labor Amt	\$1,800.00
Serial #	Appr Hrs	12.00	Appr Labor Amt	\$1,800.00

Notes

Submitted	Labor Amt	\$1,800.00	Approved	Labor Amt	\$1,800.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$1,800.00		Total	\$1,800.00

DEALER _____ DATE _____
SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE
 All repairs described have been inspected and are satisfactory.