

lease return parts to:

2425 Davis Drive
Goshen, IN 46526

Part Tag

O. number ...: 67273
N: 4YDFM0P27N4700973
aim: C3090490
aler: dba American RV Center
m number ...: 661620
m name: TV - 50" - Connexx - LED - HDTV

Part Tag : PT615107

Reason for return

MAIN TV HAS NO PICTURE PLUGGED IN TV TURNED ON AND NO PICTURE
Reason: TV FAILED
Correction: REPLACE TV

RV – Approved to purchase replacement TV locally or online. Cost should not exceed \$300.
Purchase receipt must be submitted with Claim.

Please follow these instructions to return Warranty or RGA return parts on Keystone's account. Further information is available in Section 11 of the Policy and Procedure Manual.

Small Parts – UPS

Key Express, select 'UPS Return Label' which will take you to the UPS website to generate a return shipping label on Keystone's account. You will need the box weight (no dimensions are needed). Properly protect the contents, put the Part Return Tag inside the box, the UPS return label on the box, and have the UPS driver take the package when they deliver next.

Large Parts - Motor Freight

Also Contact CEVA Logistics at 800/989-9052 or UPS Supply Chain at 574/234-7192. They will manifest the return to Keystone Freight Collect on Keystone's account. The Warranty Claim number or RGA number will be required and the Parts Tag(s) needs to be in the package with the return. CANADA-Please see Section 11 of the Policy and Procedure Manual for complete part return instructions utilizing Frontier Supply Chain solutions.

Vendor Direct

Follow the instructions on the Warranty Claim for return of the part direct to the vendor. Do not return the part to Keystone.