

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 80721
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11827 - 2027 SPRINGDALE 2620BHS 4YDTSGM27V7100426
VIN: 4YDTSGM27V7100426 HIN: SER#: 4YDTSGM27V7100426
Mileage: 0 Work Order Comp: 20 AUG 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 28 JUL 26 Inv #: 434008

WO # Job # Description JOB INFORMATION

80721 1 WINDOW TRIM IN BEDROOM IS BENT
Window ring
During pdi noticed the windows trim ring went bent up and leaving gaps between windows and wall where it was bent at. Removed all screws in trim ring. Could not find tag. Cut all foam and pulled widnow from wall. Removed old foam. Picture of taken taken for parts request. Placed new foam on windows. Placed back in hole and secured with ring and screws. Parts request submitted for new windows trim ring. Recieved new windows and ring. Removed screws in trim ring. Pulled window out of wall. Grabbed new window and ran foam around window. Placed in wall and secured trim with screws. Went outside and siliconed top of window.

80721 2 WATER PUMP IS PULSING
Water pump pulses
During pdi noticed that the water pump pulses when running. Pictures taken. Parts request submitted for new pump. Recived new puu,p. Removed all four screws holding pump in. Cut wires to pump. Disconnected water lines to pump. Removed filter from old pump and placed on new. Placed pump in position. Had to angle drill in a specific way to fit and se ure screw from pump to wall. Secured pump. Attached water lines. Turned on pump and checked for leaks. None found. Placed cover back on over pump and water heater.

Part No Job# Description PARTS Qty Price Total

626641 1 Window - 30" x 20" - Horizontal S 1.00 111.37 111.37

Claim : 80721

```

*****
Part No      Job#  Description          PARTS          Qty    Price    Total
*****
789650       2    Pump - Water - 3.0 GPM - 12V - w/  1.00    55.58    55.58

```

```

*****
Lab Code Job#  Description          LABOUR          Hrs     Rate    Total
*****
Z990      1    MISCELLANEOUS REPAIR          0.20    190.00    38.00
Z990      1    MISCELLANEOUS REPAIR          0.00    190.00     0.00
Z990      2    MISCELLANEOUS REPAIR          0.10    190.00    19.00
Z990      2    MISCELLANEOUS REPAIR          0.10    190.00    19.00
Z990      2    MISCELLANEOUS REPAIR          0.15    190.00    28.50
Z990      2    MISCELLANEOUS REPAIR          0.15    190.00    28.50

```

```

*****
Excode Job#  Description          EXTRAS          Qty    Price    Total
*****
FRT      1    UPS-WINDOW          1.00    39.00    39.00
FRT      2    UPS-PUMP            1.00    12.57    12.57

```

```

Parts Total: 166.95
Labour Total: 133.00
Sublet Total: 0.00
Extras Total: 51.57

```

>>>> Claim Total: 351.52

Customer Signature: _____

Date: _____