

GREENEWAY, INC.  
8220 STATE HWY 13 SOUTH  
WISCONSIN RAPIDS WI  
US  
54494  
(715) 325-5170

WORK ORDER # 13779

|                 |                     |                 |                        |
|-----------------|---------------------|-----------------|------------------------|
| Date In:        | 10 JUL 26           | Author:         | DMCGINLEY              |
| Promised Date:  | 18 AUG 26           | Stock No:       | 11382                  |
| :               | :                   | Year:           | 2025                   |
| Customer Name:  | 1021 - FOREST RIVER | Manufacturer:   | FOREST RIVER           |
| Address:        | 21815 NETWORK PLACE | Brand:          | FLAGSTAFF E-PRO        |
| :               | CHICAGO, IL         | Model:          | E20FK                  |
| Postal/Zip:     | 60673-1218          | Miles/Hrs:      | :                      |
| Phone#(res):    | 219-534-3167        | Exterior Color: | :                      |
| Phone#(bus):    | 219-534-3167        | Unit Type:      | TT-TRAVEL TRAILER      |
| Cell Phone:     | :                   | License#:       | :                      |
| Email:          | NONE                | Tag#:           | WONT BE BACK UNTIL 7/2 |
| Purchased Date: | 23 JUL 25           | :               | :                      |
| Delivery Date:  | 09 AUG 25           | :               | :                      |
| InService Date: | :                   | :               | :                      |
| Serial#:        | 5ZT2FSKB9S3038196   | :               | :                      |

```
*****
Job #  Description                JOB INFORMATION                Type Bill To
*****
1      COMPLAINT:  installed faucet now seems like the pump E      80806  PEDER
                can not build pressure. - WE JUSTY
                INSTALLED THIS LAST WEEK. WORKED AS
                NORMAL BEFORE HAND.
      CAUSE:      The valve on the pump was turned the
                wrong direction. I filled the fresh
                tank to 1/3 full, turned the kitchen
                faucet on and not a lot of water was
                coming out. I located the pump, turned
                the valve, tried the kitchen faucet
                again and everything is working. I tried
                the faucet in the bathroom to verify
                its working there too and it is.
      CORRECTION: Done.
2      COMPLAINT:  BLACK TANK IS ALWAYS READS 3/4 FULL EVEN E      80806  PEDER
                WHEN EMPTY. CMR STATES "WE DO NOT FLUSH
                ANY TOILET PAPER AND ONLY USE FOR URINE.
                THEY ALSO TYPICALLY DRY CAMP, BUT WHEN
                PULLIONG WATER FROM FRESH TANK, BLACK
                TANK STILL READS 3/4."
      CAUSE:      NPF. I took the unit to our dump
                station right away, drained the black
                tank, hooked a hose up to the black tank
                flush and let it run for a few minutes.
                I shut the water off, checked the gauge
                levels and the tank is empty. I brought
                the unit inside and filled the tank to
                test it further. I put a sensor cleaner
```

Continued on page 2

Work Order : 13779

\*\*\*\*\*

| Job #                                                                                                                                                                               | Description                                                  | JOB INFORMATION | Type  | Bill To |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------|-----------------|-------|---------|
| 3                                                                                                                                                                                   | Customer requests having a showthru done on his unit         | E               | 80806 | PEDER   |
| WARR                                                                                                                                                                                | COMPLAINT: WARRANTY REPAIR 1 - water pump will not shut off. | E               | 1021  | FORES   |
| CAUSE: Water pump is running even when water isnt on its not pulsing its just constantly running, I tried adjusting pressure and nothing happened, we will have to replace the pump |                                                              |                 |       |         |
| CORRECTION: The pump was running non stop to the point it burned out the old pump, I replaced the pump and cleaned out the old screen and it is running good now                    |                                                              |                 |       |         |

\*\*\*\*\*

| Job # | Part No      | Description              | PARTS  | Bill to | Qty | Price  | Total  |
|-------|--------------|--------------------------|--------|---------|-----|--------|--------|
| WARR0 | 752324010998 | REVOLUTION AUTO DEMAND P | E-1021 |         | 1   | 157.05 | 157.05 |

\*\*\*\*\*

| Job#  | Lab Code | Description            | LABOUR | Mech    | Bill to | Hrs  | Rate   | Total  |
|-------|----------|------------------------|--------|---------|---------|------|--------|--------|
| 2     | WARR     | MANUFACTURER WARRANTY  | JGK    | E-80806 |         | 0.22 | 130.00 | 28.60  |
| 1     | Z991     | MISC CODE (INTERNAL)   | JGK    | E-80806 |         | 0.33 | 130.00 | 42.90  |
| 1     | Z991     | MISC CODE (INTERNAL)   | JGK    | E-80806 |         | 0.00 | 130.00 | 0.00   |
| 2     | WARR     | MANUFACTURER WARRANTY  | JGK    | E-80806 |         | 0.00 | 130.00 | 0.00   |
| 2     | WARR     | MANUFACTURER WARRANTY  | JGK    | E-80806 |         | 0.78 | 130.00 | 101.40 |
| 3     | Z990     | MISC LABOUR CODE (EXTE |        | E-80806 |         | 0.00 | 130.00 | 0.00   |
| ARR01 | Z992     | MISC LABOUR CODE (WARR | EG     | E-1021  |         | 0.48 | 140.00 | 67.20  |
| ARR01 | Z992     | MISC LABOUR CODE (WARR | EG     | E-1021  |         | 0.02 | 140.00 | 2.80   |
| ARR01 | DIAG     | DIAGNOSTICS            | EG     | E-1021  |         | 1.00 | 140.00 | 140.00 |
| ARR01 | RV9-24d  | WATER PUMP R&R HAND RV | EG     | E-1021  |         | 1.00 | 140.00 | 140.00 |

\*\*\*\*\*

| Job # | Excode | Description              | EXTRAS | bill to | Qty  | Price | Total |
|-------|--------|--------------------------|--------|---------|------|-------|-------|
| 1     | SSE    | SHOP SUPPLIES - EXTERNAL |        | E-80806 | 1.00 | 35.00 | 35.00 |

\*\*\*\*\*

\*\*\*\*\*

| BILLINGS SUMMARY |         |        |        |        |        |       |        |
|------------------|---------|--------|--------|--------|--------|-------|--------|
| Type             | Bill Id | Parts  | Labour | Sublet | Extras | Tax   | Total  |
| E                | 1021    | 157.05 | 350.00 | 0.00   | 0.00   | 0.00  | 507.05 |
| E                | 80806   | 0.00   | 172.90 | 0.00   | 35.00  | 11.46 | 219.36 |

\*\*\*\*\*

Continued on page 3

Work Order : 13779

\*\*\*\*\*

## BILLINGS SUMMARY

| Type Bill Id | Parts  | Labour | Sublet | Extras | Tax   | Total  |
|--------------|--------|--------|--------|--------|-------|--------|
| *****        |        |        |        |        |       |        |
| Totals       | 157.05 | 522.90 | 0.00   | 35.00  | 11.46 | 726.41 |

&k2S  
&k0S