

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67363
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52193 - MARK SPIEHLER
Address: 10215 CLUBHOUSE DR EVANSVILLE, IN

47725

Phone: 812-319-2757

Stock Number: 10995 - 2022 APEX 265RBSS 5ZT2CXSB1NS042985

VIN: 5ZT2CXSB1NS042985 HIN: SER#: 5ZT2CXSB1NS042985

Mileage: 0 Work Order Comp: 26 MAY 22

Auth. No: Dealer #:

Warr. Date: 21 JAN 22 Work Order Date: 07 MAY 22 Inv #: 377476

WO # Job # Description JOB INFORMATION

67363 2 CEILING LIGHT ABOVE KITCHEN IS FLASHING
BJ CALLED CUSTOMER TO SEE WHICH LIGHT IS HAVING THE ISSUE. DIDNT
SEE ANY FLASHING ON ANY OF THE LIGHTS IN THE CAMPER. 5/11/22
VERIFIED WHICH LIGHT IS FLASHING. WAITING ON PARTS AND APPROVAL.
removed faulty light. tagged and put in parts room. installed new
light and secured to ceiling.

67363 3 SHOWER DOOR TRACK AT BOTTOM IS LEAKING WATER
SHOWER SURROUND WAS NOT SEALED AT ALL FROM FACTORY.
APPLIED SILICONE TO INSIDE AND OUTSIDE OF SHOWER SURROUND TRACK
AND IN BOTH CORNERS

67363 2V243 RECALL 22V243 LP QUICK CONNECT
unit is not equiped with a quick connect
no correction

67363 4 AC IS NOT RUNNING PROPERLY. WILL ONLY RUN FOR A SHORT TIME THEN
KICK OFF BEFORE THE TEMP GETS TO THE SET TEMP.
thermostat is dropping temp very fast and is shutting down the
a/c before the room reaches desired temp. the room sensor is
located inside the shroud of the a/c. pulled shroud off and the
divider was not sealing properly and allowing cold air to blow
through and is hitting the room sensor.
taped up divider with aluminum tape to cover all the gaps. pulled
room sensor as far away from the divider as i could. ran a/c to
test. thermostat is reading ambient air as it should.

Claim : 67363

 WO # Job # Description JOB INFORMATION

 Part No Job# Description PARTS Qty Price Total

 C01297663 2 4.5 INCH LED LIGHT 1.00 3.38 3.38
 500627 3 SILICONE - N PLUS - CLEAR 1.00 17.86 17.86

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 150.00 30.00
 Z990 V243 MISC LABOUR CODE (EXTERNAL) 0.10 150.00 15.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.80 150.00 120.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 2 UPS-LIGHT 1.00 15.99 15.99

Parts Total: 21.24
 Labour Total: 195.00
 Sublet Total: 0.00
 Extras Total: 15.99

>>>> Claim Total: 232.23

Customer Signature: _____

Date: _____