



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67441
Promised Date: 28 MAY 22

CUSTOMER WORK ORDER

WO #: 67441

Customer: 41028 - RUSSELL, JOHN R. -
812-270-1292

Tag: NOT HERE

Author: BJW

Location: 0701 TALK TO BH ABOUT
NEEDED REFRIGERATOR DOOR

Stock #: 10722

Stock Desc: 2021 5W KEYSTONE
SPRINGDALE 340FWBH

Chassis #: 4YDF3402XM3110422

Serial #: 4YDF3402XM3110422

Mileage: 0

Licence:

Invoice #:

Date In: 16 MAY 22

Promised: 28 MAY 22

Date Sched:

Completed: 30 JUN 22

Warr. Date: 19 JUN 21

Job #1 - Warranty

COMPLAINT: THE ROOF AC ONLY BLOWS HOT AIR AFTER SEVERAL ATTEMPTS TO GET WORKING THIS WEEKEND.

CAUSE: PULLED UNIT INTO SHOP. TURNED ON A/C. A/C WILL NOT COOL AS STATED. REMOVED INSIDE SHROUD. HOOKED UP SHOP TESTER AND CYCLED THROUGH FUNCTIONS. COMPRESSOR IS TURNING ON AND IS RUNNING AT PROPER AMP DRAW "9-10" COMPRESSOR IS NOT COOLING.

CORRECTION: REMOVED INSIDE SHROUD. REMOVED CONTROL BOX. REMOVED LAG BOLTS FROM A/C. REMOVED METAL MOUNTING FRAME AND DIVIDER. REMOVED PLUG FROM CONTROL BOX TOOK FORK TRUCK AND REMOVED A/C FROM ROOF. REMOVED NEW A/C FROM BOX. POSITIONED ON ROOF. INSTALLED LAG BOLTS, FRAME, CONTROL BOX, APPLIED ALUMINUM TAPE TO INSIDE DIVIDER. PLUGGED IN A/C TO CONTROL BOX. INSTALLED SHROUD. TESTED A/C. BEN CONFIRMED THIS IS WORKING

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	96.00
Z990	MISCELLANEOUS REPAIR	ZMS	6.00
Z990	MISCELLANEOUS REPAIR	ZMS	48.00

Parts

Part #	Description	Qty	Price	Total
647993	A/C - 15.0 BTU - G	1.00	699.20	699.20

Other Services

Code	Description	Qty	Price	Total
FRT	CEVA FREIGHT - A/C UNIT	1.00	169.84	169.84

Subtotal for Job #1: 1,019.04

Job #2 - Warranty

COMPLAINT: THE INSIDE REFRIGERATOR QUIT WORKING ALTHOUGH THE FREEZER STILL WORKS.

CAUSE: TURNED ON FRIDGE AND RAN OVER THE WEEKEND. FREEZER HAD A LOT OF ICE BUILD UP. NUMBER 4 LIGHT WAS FLASHING ON TEMP CONTROL BOARD. THIS CODE IS FOR A FAN FAULT. NEED TO LET THAW OUT AND CONTINUE TESTING 5/23/22

CORRECTION: REMOVED FAN ASSEMBLY FROM FREEZER TO CHECK FOR FUNCTION AND POWER. FAN HAS POWER AND IS WORKING. PUT FLASHLIGHT INSIDE FREEZER DOOR AND NOTICED A GAP BETWEEN THE GASKET AND THE FREEZER DOOR. ORDERED NEW GASKET. AFTER FURTHER TESTING THERE IS A GAP BETWEEN THE FRIDGE DOOR AND GASKET. FRIDGE



Customer #: 41028
RUSSELL, JOHN R.



DOOR WAS TOO LOW. ADDED 3 PLASTIC SHIMS TO BOTTOM BRACKET TO RAISE UP DOOR.
 TOOK A HEAT GUN ACROSS BOTH GASKETS WHERE THEY WERE NOT SEALING. GASKETS ARE
 SITTING FLUSH AGAINST FRIDGE. LETTING TEST TO SEE IF THE ISSUES ARE RESOLVED 6/7/22
 FRIDGE RAN OVER THE WEEKEND WITH NO ISSUES

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	30.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00
Z990	MISCELLANEOUS REPAIR	ZMS	0.00

Parts

Part #	Description	Qty	Price	Total
693067	Refrigerator - Seal - Freezer Door - For BCD280WEV804H-6	1.00	87.18	87.18

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DOOR SEAL	1.00	27.41	27.41

Subtotal for Job #2: 144.59

Job #3 - Internal

COMPLAINT: THE COACH CO/PROPANE MONITOR WOULD NOT STOP ALARMING

CAUSE: removed electrical tape customer put over alarm. had unit in the shop hooked up to shore power
 over the weekend. alarm didnt go off at any point during testing of jobs 1 and 2. these alarms will sound
 when voltage is too low. denny wants to replace co2 alarm.

CORRECTION: REMOVED OLD MONITOR. INSTALLED NEW MONITOR

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	ZMS	N/C
Z990	MISCELLANEOUS REPAIR	ZMS	N/C

Parts

Part #	Description	Qty	Price	Total
636092	Alarm - LP/CO - Co	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DETECTOR	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 786.38
 Labour Total: 180.00
 Sublet Total: 0.00
 Extras Total: 197.25
WORK ORDER TOTAL: 1,163.63

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited
 to work performed. Consequential damages are not covered. All guaranteed work
 must be completed in our service department.



Customer Signature : _____

Date: 01 Jul 2022

W/O: 6241
Promis-4 Date: 28 MAY 22



Customer #: 41028
RUSSELL, JOHN R.

