



12024 Central Ave SE ★ Albuquerque NM 87123
www.MYERSRV.com
(505)298-7691 ★ 1-800-748-2078 ★ FAX (505)293-7172

W/O: 73765
Promised Date:
44 AUG 26



WO #: 73765 (Appointment Date: 25 JUL 2026 - Time: 10:15am)

Customer Name: 60490 - RODRIGUEZ, TERESA

Completed Date:

Invoice#:

Author: ADVISOR

Stock Desc: 9486 2025 AVENGER 16RD

Serial#: 5ZT2AVEC7SB939707

Chassis#: 5ZT2AVEC7SB939707

Miles/Hrs:

Tag#: 7420

Purchased Date: 09 AUG 25

Warranty Date: 09 AUG 25

Date In: 25 JUL 26

Time In:

Job #1 - Warranty

COMPLAINT: CUSTOMER STATES THEIR IS A LEAK IN THE GREY TANK PIPE AND IS LEAKING FROM UNDERBELLY. **CUSTOMER SENT IN VIDEO**

CAUSE: Failed plumbing on drain from shower

CORRECTION: Drop underbelly. Remove failed plumbing. Install new plumbing from shower to grey tank. Reinstall underbelly. Test and reseal underbelly. Requesting 5.0 hrs

Labor

Job #	Description	Total
1	WATER TANK INSPECT FOR LEAKS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: CUSTOMER STATES THE KITCHEN FAUCET IS LEAKING

CAUSE: Leaking past seals

CORRECTION: Replace faucet
Requesting 1.0 hr

Labor

Job #	Description	Total
2	FAUCET R&R KITCHEN	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES BLACK TANK FLUSH HANDLE IS GETTING STUCK

CAUSE: Seal obstruction.

CORRECTION: Replace 3 waste valve assembly
Requesting 2.0 hrs

Customer #: 60490
RODRIGUEZ, TERESA





Labor				
Job #	Description			Total
3	BLACK TANK HANDLE			N/C
Parts				
Part #	Description	Qty	Price	Total
13-0108	AQUA-MAX 32OZ LIQUID	1.00	N/C	N/C
Subtotal for Job #3:				0.00

Job #4 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES PANEL IN BATHROOM IS COMING APART

CAUSE: Vanity mirror panel has stripped out hardware.

CORRECTION: Remove vanity. Fill holes. Reinstall vanity. Glue and screw for additional security.
 Requesting.5 hr

Labor				
Job #	Description			Total
4	MONITOR PANEL R&R WALL MOUNT			N/C
Subtotal for Job #4:				0.00

Job #5 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES SWITCH COVER ON TONGUE JACK CAME OFF

CAUSE: Missing

CORRECTION: Replace
 .5 hr

Labor				
Job #	Description			Total
5	SWITCH COVER			N/C
Subtotal for Job #5:				0.00

Job #6 - Warranty

COMPLAINT: JOB ADDED: CUSTOMER STATES ALL THE COMPARTMENT DOOR LOCKS ARE LOOSE

1 - ONE ON DRIVERS SIDE
 2 - ON PASSENGER SIDE

CAUSE: Out of adjustment

CORRECTION: Adjusted and tightened. Tested all locks and latches. Requesting.5 hr

Labor				
Job #	Description			Total
6	COMPARTMENT DOORS ADJUST (3)			N/C
Subtotal for Job #6:				0.00

Parts Total: 0.00
 Labour Total: 0.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 0.00



NOTICE:
DUE TO A LACK OF SPACE, A \$15/DAY STORAGE FEE WILL APPLY IF YOU DO NOT PICK UP YOUR UNIT WITHIN 48 HOURS OF NOTICE OF COMPLETION

EFFECTIVE 01/12/2026 A CREDIT CARD SURCHARGE OF 3% WILL BE APPLIED TO ALL CREDIT CARD TRANSACTIONS

MANUFACTURER'S WARRANTIES AND SERVICE CONTRACTS DO NOT COVER DIAGNOSTIC TIME IF NO PROBLEM IS FOUND

ALTHOUGH WE TAKE PRECAUTIONS TO INSURE YOUR VEHICLE'S SECURITY WHILE IN FOR REPAIRS, WE ARE NOT RESPONSIBLE FOR ANY LOSS OR DAMAGE TO THE VEHICLE OR CONTENTS DUE TO FIRE, THEFT, OR ANY OTHER CAUSE BEYOND OUR CONTROL. WE WOULD APPRECIATE YOUR ASSISTANCE BY REMOVING OR SECURING YOUR VALUABLES SUCH AS GUNS, CAMERAS, JEWELRY, CASH, ETC.

I hereby authorize Myers RV Center, Inc. to perform the repair work set forth in this work order, including the parts and materials necessary. I agree that you are not responsible for delays caused by unavailability of parts or delays in parts shipments by the supplier or transporter. I hereby grant you and/or your employees permission to operate the vehicle herein described on streets and highways for the purpose of testing, inspection or transporting to sublet vendors. An express mechanics lien is hereby acknowledged on the herein described vehicle to secure the payment for repairs performed.

Customer Signature : _____

Date: 13 Aug 2026

W/O: 73765
Promised Date: 14 AUG 26



Customer #: 60490
RODRIGUEZ, TERESA



Customer Work Order

