

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 67503  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 52657 - KRISTOPHER S. RIDEOUT  
Address: 1412 S HELFRICH AVE EVANSVILLE, IN

47712

Phone: 812-205-1227

Stock Number: 11028 - 2022 CATALINA SUMMIT SERIES 184BHS 5ZT2CAGC7NK003803  
VIN: 5ZT2CAGC7NK003803 HIN: SER#: 5ZT2CAGC7NK003803  
Mileage: 0 Work Order Comp: 31 MAY 22  
Auth. No: Dealer #:  
Warr. Date: 24 MAY 22 Work Order Date: 23 MAY 22 Inv #: 377754

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
67503 1 BLACK TANK FLUSH IS LEAKING ALSO IS MOUNTED SIDEWAYS  
REMOVED VALVE TO CHECK FOR CRACKS. I DID NOT SEE ANY CRACKS. I  
TESTED THE VALVE OUTSIDE THE CAMPER AND IT IS WORKING AS IT  
SHOULD. I CHECKED THE CONE WASHERS AND ONE SIDE LOOKED LIKE IT  
NEVER MADE CONTACT WITH THE VALVE. I CHANGED THE CONE WASHER AND  
IT DID NOT FIX THE PROBLEM. I CHANGED THE 90 DEG. FITTING AND IT  
STOPPED LEAKING. THEN I WAS ABLE TO PUT IT ALL BACK TOGETHER.  
  
67503 2 TOILET VALVE LEAKING  
REMOVED THE LINE GOING TO THE TOILET VALVE AND CHECKED THE  
FITTINGS. I SEEN THAT THE INSIDE CONE WASHER WAS NOT MAKING  
CONTACT WITH THE VALVE. I WAS ABLE TO TIGHTEN THE FITTING WITH A  
WRENCH AND GET THE LEAK TO STOP.  
  
67503 3 FIX LOWER RIGHT NOSE CAP ON THE DOOR SIDE  
LOWER 4 SCREWS DID NOT GO INTO ANYTHING ON THE TRIM. I REMOVED  
THE 4 SCREWS AND REINSTALLED THEM AT AN ANGLE. I WAS ABLE TO GET  
THEM TO BIT INTO SOME WOOD AND ADDED 2 SCREWS TO HELP HOLD THE  
TRIM DOWN.  
  
67503 4 SLIDE ROOM SEAL ON THE FRONT AND REAR IS FALLING DOWN  
I PUT THE BOLB SEALS BACK IN PLACE AND THEY FELL RIGHT OFF AGAIN.  
SO I PUT THEM BACK ON AND THEN PUT A SCREW AT THE BASE TO HOLD  
THEM IN PLACE.  
  
67503 5 SHOWER WALLS ARE COMING OFF THE WALL

Claim : 67503

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*  
                  SEALED UP AROUND SHOWER AND GLUED THE SHOWER WALL BACK ONTO THE  
                  OUTSIDE WALL.

\*\*\*\*\*  
 Part No      Job#      Description      PARTS      Qty      Price      Total  
 \*\*\*\*\*  
 10-7150            1      CONE WASHER SWIVEL            1.00      0.26      0.26  
 72-0839            1      Fresh Water Adapte            1.00      2.58      2.58

\*\*\*\*\*  
 Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*  
 Z990            1      MISC LABOUR CODE (EXTERNAL)      0.50      150.00      75.00  
 Z990            2      MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00  
 Z990            3      MISC LABOUR CODE (EXTERNAL)      0.10      150.00      15.00  
 Z990            4      MISC LABOUR CODE (EXTERNAL)      0.30      150.00      45.00  
 Z990            5      MISC LABOUR CODE (EXTERNAL)      0.15      150.00      22.50  
 Z990            5      MISC LABOUR CODE (EXTERNAL)      0.15      150.00      22.50

Parts Total:            2.84  
 Labour Total:          195.00  
 Sublet Total:          0.00  
 Extras Total:          0.00

>>>> Claim Total:      197.84

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_