



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27546



WO #: 27546 (Appointment Date: 07 AUG 2026 - Time: 01:30pm)

Customer: 67451 - MOORMAN, ANTHONY
Address: 5280 LONESOME PINE TR.
GREENEVILLE, TN
37745

Home Phone: (423) 620-8539

Work Phone:
Author: S.DAVIS

Location: IH

Invoice #:

Stock #: 11150

Stock Desc: (11150) 2026 DUTCHMEN ASTORIA
298BH

Model: 298BH

Serial #: 4YDFAAP25TZ915072

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 06 JUL 26

Date In: 06 AUG 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 06 JUL 26

Job #1 - External

SC TO KINSER PARK LOT 102

THIS SERVICE CALL FEE WAS WAIVED

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: INTERIOR TRIM ON SLIDE OUT CAME OFF WHILE UNIT WAS TRAVELING

CAUSE: VERIFIED TRIM CAME LOOSE FROM WALL.

CORRECTION: REATTACH TRIM BACK INTO TO PLACE
LABOR .20

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: SMALL ESCAPE DOOR HAS LIGHT SHOWING AT THE BOTTOM
CUST WILL SHOW TECH THE DOOR

CAUSE: TECH VERIFIED WITH PHOTO THAT THE DOOR IS ALLOWING LIGHT IN AT THE BOTTOM.
TECH DID TRY TO ADJUST THE DOOR AND FIX THE ISSUE HOWEVER, THIS DID NOT FIX THE
ISSUE.

CORRECTION: REPLACE DOOR TO CORRECT ISSUE
LABOR FOR REPLACEMENT OF DOOR AND ADJUSTMENT
LABOR 1.0

Subtotal for Job #3: 0.00

Job #4 - External

COMPLAINT: 2 KITCHEN CABINETS OVER SINK WILL NOT SHUT
CUST STATED THIS COULD BE THE MAGNETS THAT HOLD THEM SHUT

CORRECTION: NO ISSUES FOUND AT THIS TIME.

Customer #: 67451
MOORMAN, ANTHONY



Subtotal for Job #4: 0.00

W/O: 27546

Parts Total: 0.00

Labour Total: 0.00

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.

X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 13 Aug 2026



Customer #: 67451
MOORMAN, ANTHONY



Customer Work
Order

