



Phone: (423) 235-1167
Toll Free: (877) 635-1167
Fax: (423) 235-1176

1202 Idell Road
Bulls Gap, TN 37711

W/O: 27485



WO #: 27485 (Appointment Date: 31 JUL 2026 - Time: 11:00am)

Customer: 93820 - FELTS, RONALD
Address: HOUSE 82 NEW CAMP HILL RD
WILCOE, WV
24801

Home Phone:

Work Phone:

Author: SPD

Location: IH

Invoice #:

Stock #: 11184

Stock Desc: (11184) 2026 FOREST RIVER

SANDPIPER 3370RLS

Model: 3370RLS

Serial #: 4X4FSAK20TJ048566

Chassis #:

Mileage:

Key #:

Req'n #:

License #:

Trim:

Purchase Date: 14 JUL 26

Date In: 22 JUL 26

Promise Date:

Promise Time:

Schedule Date:

Completed:

Warr. Date: 14 JUL 26

Job #1 - External

SC SMOKEY WATER CAMPGROUND LOT 90 (SONS # 304-888-2258) TIM FELTS

Other Services

Code	Description	Qty	Price	Total
SSE	SHOP SUPPLIES EXTERNAL	1.00	0.00	0.00

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: THERE IS A LEAK COMING IN THROUGH THE INTERIOR WALL, FLOOR NEXT TO BAR IS SQUEAKING CHECK AND ADVISE

CAUSE: TECH FOUND OPEN VOIDS AROUND THE SKYLIGHT AND VENTS ALLOWING WATER AND MOISTURE.

CORRECTION: CLEAN AND RESEAL UP VOIDS
LABOR .50

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CUSTOMER STATES HIS BATHROOM SINK IS BUBBLING

CAUSE: OVERLAY IS COMING LOOSE ON SINK COUNTER TOP.

CORRECTION: REPLACE THE BATHROOM COUNTER TOP
NEED TO REMOVE AND REINSTALL FAUCET TO REPLACE COUNTER
LABOR 2.0

Subtotal for Job #3: 0.00

Job #4 - Warranty

COMPLAINT: SOFT CLOSE DRAWER NOT STAYING CLOSED

CAUSE: FAULTY DRAWER GUIDE

CORRECTION: REPLACE DRAWER GUIDE
LABOR .50

Customer #: 93820
FELTS, RONALD



Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: DINETTE CHAIR PAINT IS COMING OFF IN DIFFERENT AREAS

CAUSE: PAINT FROM BUILD IS FADING AND COINF OFF THE CHAIR

CORRECTION: REPLACE CHAIR
LABOR.10

Subtotal for Job #5: 0.00

Job #6 - Warranty

COMPLAINT: CABINET BOTTOM ON HIDDEN PANTRY IS FALLING DOWN OUT OF PLACE.

CAUSE: BOARD NOT SECURED IN PLACE AT BUILD AND HAS FALLEN DOWN

CORRECTION: REMOVE THE SIDE MOLDING ON THE BOTTOM AND RESECURE BOARD BACK IN
CORRECT PLACE
LABOR 1.0

Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES THE BLACK TANK WILL NOT EMPTY. STATES ON THE NATALUS,
WHEN HE PULLS THE GREY TANK IT WILL DRAIN, BUT THE BLACK TANK WILL NOT. PLEASE
CHECK AND ADVISE

CORRECTION: CUST CALLED AND ADDED THIS AFTER THE SERVICE CALL. WILL ADDRESS AT A
LATER DATE,NO WORK PREFORMED

Subtotal for Job #7: 0.00

Parts Total: 0.00
Labour Total: 0.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 0.00

I HEREBY ACCEPT ABOVE DESCRIBED WORK AS SATISFACTORY & COMPLETE TO MY SATISFACTION.
X

MOTOR VEHICLE REPAIR REGISTRATION #MV-04967

Customer Signature : _____

Date: 07 Aug 2026

W/O: 27485



Customer #: 93820
FELTS, RONALD

