



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67576

CUSTOMER WORK ORDER

WO #: 67576

Customer: 50475 - JONES, LORIE B. -
812-455-6969

Tag:

Author: P.HUNT

Location: 0620 CHECK TO SEE IF WE
HAVE FREIGHT YET FROM MATT

Stock #: 10990

Stock Desc: 2021 5W FOREST RIVER

SABRE 37FLH

Chassis #: 5ZT3SR2B7M6107638

Serial #: 5ZT3SR2B7M6107638

Mileage: 0

Licence:

Invoice #: 378500

Date In: 31 MAY 22

Promised:

Date Sched:

Completed: 16 JUN 22

Warr. Date: 11 NOV 21

Job #1 - Warranty

COMPLAINT: KITCHEN SLIDE NOT OPERATING

CORRECTION: BRING UNIT IN, TEST SLIDEOUT, CAN HERE MOTOR RUNNING, SLIDEROOM NOT MOVING, HAND CRACK SLIDEROOM OUT AN INCH, CUT UNDERBELLY AND TRY TO RUN SLIDEROOM OUT MOTOR RUNS BUT DOES NOT TURN SHAFT TO SLIDEROOM BRING UNIT BACK UP TO BAY, REMOVE SLIDEROOM MOTOR GRAER BOX AND ACTUATOR, INSTALL NEW PARTS WIRE UP MOTOR, TEST AND ADJUST SLIDEROOM, PUT UNDERBELLY UP

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	112.50

Parts

Part #	Description	Qty	Price	Total
10F17151A	FRAME, ACTUATOR RAM ARM 40" (ALSO FOR **TSB# 51-1377**) SHED	1.00	539.29	539.29

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	135.00	135.00

Subtotal for Job #1: 786.79

Job #2 - Warranty

COMPLAINT: FUSE LABELED BOOSTER KEEPS BLOWING, SEEMED TO ONLY BLOW EVERYTIME IT RAINED. CAUSES FRONT AC TO NOT WORK

CORRECTION: OPEN POWER PANEL, FOUND #5 BLOWING FUSE (ORANGE WIRE) PULL TV BOSTER FROM WALL AND TEST, BOSTER IS ON RED WIRE #6 MARKED BEDROOM, OPEN FRONT AC AND CHECK FOR WIRE,, PULL CONTROL PANEL AND CHECK FOR WIRES, remove customer stuff and open access panels climb in compartment and hand trace wires to furnace open out side door to furnace, remove screws holding furnace down and move over to get pliers to pull out wire connections, found wires hanging out of connections and shorting out, replace connections and test, PUT ALL PANELS, COMPONENTS AND COVERS BACK TOGETHER, RELOAD CUSTOMER STUFF, PULL OUT TO SERVICE LOT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	450.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	150.00

Subtotal for Job #2: 600.00



Customer #:
50475



Job #3 - External

COMPLAINT: LIMB KNOCKED OFF ROOF. DH CALLED
CUSTOMER

CORRECTION: PEAL OFF SEALER REMOVE OLD VENT CAP, INSTALL NEW VENT AND SEAL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
31-8490	40033 REPLACE ALL PLUMBING VENT	1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #3: 0.00

Parts Total: 539.29
Labour Total: 712.50
Sublet Total: 0.00
Extras Total: 135.00
WORK ORDER TOTAL: 1,386.79

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Dec 2022

W/O: 67576



Customer #:
50475

