

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	1075800
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKY27NK080408
USA		CHASSIS VIN	
		MILEAGE	0
		SITE/WAREHOUSE	017 / 017C
Labor rate:	\$150.00	ITEM #	CCKT23MK
OWNER INFORMATION		DEALER RO #	67597
		CLAIM START DATE	06/03/2022
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description
	10-38-01-00-000497	Lippert Schwintek In-Wall Slide Out Column - complete, per side - Frame & Chassis/Slide Out System (Lippert Schwintek)/Replace/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2022-06-03 11:58:54 :: SWINTEC SLIDE WILL NOT OPEN IN WASHBAY ON DEL DAY. SLIDEROOM WILL NOT OPEN ON BACK SIDE OF UNIT BOTTOM STOPPED AT 1 IN TOP MOVED ABOUT 3 IN OUT WAS ABLE TO PULL DOWN UOT SIDE SEAL FAR ENUF TO REMOVE MOTOR LOCKING BOLT, REMOVE BULB SEAL AND FLAP SEAL ON INSIDE, REMOVE MOTOR FROM SLIDEROOM WORKS AND TOP OF SLIDEROOM CAME BACK IN, TAKE PIC OF RAILS ON IN SIDE RUN SCOPE IN TO LOWER BLOCK NO VISABLE BLOCKAGE GET ROOM CLOSED AND TURN IN PO FOR PARTS, CAN NOT TAKE MEASUREMENTS FOR THE SHEET THE BOTTOM OF THE ROOM IS NOT MOVING NEED TO REPLACE THE SLIDE SYSTEM

Model #	Dlr Sub Hrs	3.00	Sub Labor Amt	\$450.00
Serial #	Appr Hrs	3.40	Appr Labor Amt	\$510.00

Notes

Attach forms please

I sent to the vendor 6/3/22.

Case #3237528

Thank you for contacting Lippert Components Customer Service Team. Case #3237528 has been created in response to your submission.

Ok to R&R columns and rails

Post install tolerance measurements will be required for this claim. Attach to the email thread and to the claim line.

case 3237528

Submitted	Labor Amt	\$450.00	Approved	Labor Amt	\$510.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$450.00		Total	\$510.00

DEALER
SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER
SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.