



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67597
Printed Date: 03 JUN 22

CUSTOMER WORK ORDER

WO #: 67597

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: DELIVERY 0603

Stock #: 10805
Stock Desc: 2022 TT FOREST RIVER
CHEROKEE GREY WOLF 23MK
Chassis #: 4X4TCKY27NK080408
Serial #: 4X4TCKY27NK080408
Mileage: 0
Licence:

Invoice #:
Date In: 02 JUN 22
Promised: 03 JUN 22
Date Sched:
Completed: 19 JUL 22
Warr. Date: 03 JUN 22

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CORRECTION: FPD, PULL TAPE OFF OF ICE MAKER AND MICROWAVE, DEWINTERIZE, PUMP
WATER THROUGHT SYSTEM, FOUND OUT SIDE SHOWER SPARER IS BROKEN SHUT OFF VALVE,
BLACK TANK FLUSHER IS MISSING, CHECK LIGHTS TIRES ROOF, LUG NUTS, BRAKES,
BREAKAWY, FURNACE WATER HEATER MICROWAV 2 REFERS 2 OUT SIDE SHOWERS, SHOWER
TOILET, SINKS, RADIO,

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JP	N/C

Subtotal for Job #FPDINTT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CORRECTION: INSTALL E2 ON UNIT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Subtotal for Job #E2: 0.00

Job #3 - Warranty

COMPLAINT: SWINTEC SLIDE WILL NOT OPEN IN WASHBAY
ON DEL DAY.

CORRECTION: SLIDEROOM WILL NOT OPEN ON BACK SIDE OF UNIT BOTTOM STOPED AT 1 IN
TOP MOVED ABOUT 3 IN OUT WAS ABLE TO PULL DOWN UOT SIDE SEAL FAR ENUF TO REMOVE
MOTOR LOCKING BOLT, REMOVE BULB SEAL AND FLAP SEAL ON INSIDE, REMOVE MOTOR FROM
SLIDEROOM WORKS AND TOP OF SLIDEROOM CAME BACK IN, TAKE PIC OF RAILS ON IN SIDE
RUN SCOPE IN TO LOWER BLOCK NO VISABLE BLOCKAGE GET ROOM CLOSED AND TURN IN PO
FOR PARTS, CAN NOT TAKE MEASUREMENTS FOR THE SHEET THE BOTTOM OF THE ROOM IS
NOT MOVING

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	300.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	210.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00



Customer #: 1000
BASDEN'S AMERICAN RV,

Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JP	N/C

Parts

Part #	Description	Qty	Price	Total
6544	SLIDEROOM SYSTEM (RACK)	1.00	820.92	820.92

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-SLIDE PARTS	1.00	35.00	35.00

Subtotal for Job #3: 1,365.92

Parts Total: 820.92
 Labour Total: 510.00
 Sublet Total: 0.00
 Extras Total: 35.00
WORK ORDER TOTAL: 1,365.92

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 19 Jul 2022

Customer #: 1000
 BASDEN'S AMERICAN RV,

