



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 678  
Promised Date: 25 JUN 22

### CUSTOMER WORK ORDER

WO #: 67608

Customer: 18834 - EGLI, MARK J. -  
812-682-2594

Tag:  
Author: BH

Location: 1101 CALL CUSTOMER SEE IF  
CUSTOMER HAS BROUGHT CAMPER  
BACK TO WINTERIZE IT

Stock #: 10676  
Stock Desc: 2022 TT COACHMEN  
CATALINA 243RBSLE  
Chassis #: 5ZT2CANB2NU039607  
Serial #: 5ZT2CANB2NU039607  
Mileage: 0  
Licence:

Invoice #:  
Date In: 03 JUN 22  
Promised: 25 JUN 22  
Date Sched:  
Completed: 09 JUL 22  
Warr. Date: 29 APR 22



#### Job #3 - Warranty

COMPLAINT: THERE IS A CRACK IN THE FRONT LEFT  
CORNER OF THE KITCHEN SINK

CAUSE: SINK HAD CRACK IN IT ORDERED NEW SINK

CORRECTION: REMOVED DRAWERS .REMOVED DRAIN. REMOVED SINK. CLEAN OFFSILICONE  
AROUND COUNTER TOP. INSTALL NEW SINK. PUT DRAIN BACK AND SILICONED

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	75.00
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Parts Part #	Description	Qty	Price	Total
F100281435	SINK, KITCHEN PLAS	1.00	29.04	29.04

Other Services Code	Description	Qty	Price	Total
FRT	UPS-SINK	1.00	33.73	33.73

**Subtotal for Job #3: 137.77**

Parts Total: 29.04  
Labour Total: 75.00  
Sublet Total: 0.00  
Extras Total: 33.73  
**WORK ORDER TOTAL: 137.77**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 18 Jul 2022

Customer #: 18834  
EGLI, MARK J.



BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
 600 E. Baseline Rd.  
 Evansville, IN  
 47725  
 812-867-5200

WARRANTY CLAIM # 67608  
 MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
 Customer: 18834 - MARK J. EGLI  
 Address: 517 STEAMMILL ST. PO BOX 455 NEW HARMONY, IN  
 47631  
 Phone: 812-682-2594  
 Stock Number: 10676 - 2022 CATALINA 243RBSLE 5ZT2CANB2NU039607  
 VIN: 5ZT2CANB2NU039607 HIN: SER#: 5ZT2CANB2NU039607  
 Mileage: 0 Work Order Comp: 09 JUL 22  
 Auth. No: Dealer #:  
 Warr. Date: 29 APR 22 Work Order Date: 03 JUN 22 Inv #: 379667

\*\*\*\*\*  
 WO # Job # Description JOB INFORMATION  
 \*\*\*\*\*  
 67608 3 THERE IS A CRACK IN THE FRONT LEFT CORNER OF THE KITCHEN SINK  
 SINK HAD CRACK IN IT ORDERED NEW SINK  
 REMOVED DRAWERS .REMOVED DRAIN. REMOVED SINK. CLEAN OFFSILICONE  
 AROUND COUNTER TOP. INSTALL NEW SINK. PUT DRAIN BACK AND  
 SILICONED

\*\*\*\*\*  
 Part No Job# Description PARTS Qty Price Total  
 \*\*\*\*\*  
 F100281435 3 SINK, KITCHEN PLAS 1.00 29.04 29.04

\*\*\*\*\*  
 Lab Code Job# Description LABOUR Hrs Rate Total  
 \*\*\*\*\*  
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00  
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.50 150.00 75.00  
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.00 150.00 0.00

\*\*\*\*\*  
 Excode Job# Description EXTRAS Qty Price Total  
 \*\*\*\*\*  
 FRT 3 UPS-SINK 1.00 33.73 33.73

Parts Total: 29.04  
 Labour Total: 75.00  
 Sublet Total: 0.00  
 Extras Total: 33.73

>>>> Claim Total: 137.77