



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67748
Promise Date: 25 JUN 22

CUSTOMER WORK ORDER

WO #: 67748

Customer: 44932 - SUTTON, DENNIS A.
- 812-646-1059

Tag:

Author: BJW

Location: 0729 CHECK SYTATUS WITH
BB

Stock #: 10943

Stock Desc: 2022 TT COACHMEN

CATALINA 303RKDSLE

Chassis #: 5ZT2CAVB3NX024693

Serial #: 5ZT2CAVB3NX024693

Mileage:

Licence:

Invoice #:

Date In: 17 JUN 22

Promise: 25 JUN 22

Date Sched:

Completed: 27 JUL 22

Warr. Date: 19 MAY 22

Job #1 - Warranty

COMPLAINT: THERE IS A STAIN IN THE CARPET ABOUT THE SIZE OF A HALF DOLLAR IN FRONT OF THE COUCH.

CORRECTION: MOVED SLIDEOUT OUT THEN CHECKED TO MAKE SURE CARPET WAS THE SAME COLOR.REMOVED THE COUCH AND DINETTE SET. PULLED CARPET UP, THEN LAYED NEW CARPET DOWN AND STAPLED IN PLACE. PUT COUCH AND DINETTE SET BACK IN.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	450.00

Parts

Part #	Description	Qty	Price	Total
F100303085	CARPET, BINDED, 155.75 X 48 32BHDS LR GREY	1.00	71.32	71.32

Other Services

Code	Description	Qty	Price	Total
FRT	UPS- CARPET	1.00	32.03	32.03

Subtotal for Job #1: 553.35

Job #22V243 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

RECALL 22V243 LP QUICK CONNECT

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #22V243: 0.00

Job #2 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

ALL THREE STORAGE COMPARTMENTS DOORS ARE VERY HARD TO LOCK AND UNLOCK.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	0.00

Subtotal for Job #2: 0.00



Customer #: 44932
SUTTON, DENNIS A.



Customer #: 44932
 SUTTON, DENNIS A.



Job #3 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

THE LIGHT COVER IN THE MASTER BEDROOM NEAREST THE CLOSET IS DEFECTIVE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	RAB	0.00

Subtotal for Job #3: 0.00

Job #4 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

THERE IS TRIM MISSING IN THE BOTTOM OF THE BEDROOM SLIDE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #4: 0.00

Job #5 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

THE RIGHT BRACKET ON THE BOTTOM KITCHEN DRAWER IS LOOSE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #5: 0.00

Job #6 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

THE CAMERA ANTENNA IS LOOSE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #6: 0.00

Job #7 - Warranty

Transferred to BAS*68087 on 27 JUL 22

Estimate amount was 0.00

CHECK THE ELECTRICAL WIRING COVER NEAR THE END THAT PLUGS INTO THE TRUCK. THERE ARE WIRES SHOWING.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #7: 0.00



W/O: 6718
Promise Date: 25 JUN 22



Customer #: 44932
SUTTON, DENNIS A.



Parts Total:	71.32
Labour Total:	450.00
Sublet Total:	0.00
WORK ORDER TOTAL:	553.35

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Jul 2022

