

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67809
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52477 - DAVID A. SHADOWEN
Address: 170 N POOLE RD MADISONVILLE, KY

42431

Phone: 270-875-6245

Stock Number: 10693 - 2022 CATALINA 243RBSLE 5ZT2CANB1NU039954

VIN: 5ZT2CANB1NU039954 HIN: SER#: 5ZT2CANB1NU039954

Mileage: 0 Work Order Comp: 30 JUN 22

Auth. No: Dealer #:

Warr. Date: 06 MAY 22 Work Order Date: 23 JUN 22 Inv #: 379264

WO # Job # Description JOB INFORMATION

67809 1 SHOWER LEAKS UNDER THE SHOWER PAN AND ALSO WILL NOT DRAIN
SHOER LEAKS AND WOULDNT DRAIN DUE TO CONNECTIONS NOT BEING TIGHT
AND SEAL BEING LOSE BLOCKING DRAIN PATH
TIGHTEN LINES AND REPOSITIONED SEAL AND TESTED

67809 2V243 RECALL 22V243 LP QUICK CONNECT
RECALL ON 22V243 LP QUICK DISCONNECT
INSTALLED NEW LP QUICK DISCONNECT AND TETSTED

67809 3 CHECK WINDOW BEHIND THE SINK FOR A LEAK. NOTICED WATER ON
COUNTERTOP AFTER HARD RAIN
WINDOW WAS NOT COMPLETLEY SEALED UP ON THE OUTSIDE CAUSING WATER
COME IN
SEALED WINDOW UP AND RAN WATER OVER IT FOR 20 MINS TO CHECK FOR
LEAKS

67809 4 BLINDS BEHIND THE COUCH WILL NOT GO UP OR DOWN. CUSTOMER PULLED
THE STRING BY ACCIDENT
BLINDS BEHIND COUCH WILL NOT GO UP OR DOWN DUE TO SRINGS NOT
BEING WRAPPED ARROUND HOLDER
WRAPPED STRING AROUND HOLDER AND TETSTED

Lab Code Job# Description LABOUR Hrs Rate Total

Z990 1 MISC LABOUR CODE (EXTERNAL) 0.30 150.00 45.00

Claim : 67809

Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	V243	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.10	150.00	15.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	150.00	15.00

Parts Total: 0.00
Labour Total: 120.00
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 120.00

Customer Signature: _____

Date: _____