



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 67810
Promise Date: 30 JUL 22

CUSTOMER WORK ORDER

WO #: 67810

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0730 BH IS WAITING FOR
JOEDAY TO GET HIM INVOICE

Stock #: 11224
Stock Desc: 2022 5W FOREST RIVER
SABRE 36BHQ
Chassis #: 5ZT3SR1B9N6111984
Serial #: 5ZT3SR1B9N6111984
Mileage: 0
Licence:

Invoice #:
Date In: 23 JUN 22
Promised: 30 JUL 22
Date Sched:
Completed: 31 JUL 22
Warr. Date:

Job #PDINFW - Internal

COMPLAINT: Transferred to BAS*67875 on 01 JUL 22
Estimate amount was 0.00
PDI - NEW FIFTH WHEEL

CAUSE: PDI

CORRECTION: CHECKED APPLIANCES, BRAKES, RUNNING LIGHTS, TIRE PRESSURE, HOLDING
TANKS, WATER AND PLUMBING SYSTEM, ELECTRICAL SYSTEM, DOORS AND CABINETS, FILLED LP,
RAN LP DROP TEST, CHECKED ROOF

Labor

Code	Description	Mechanic	Total
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C
Z991	PDI NEW FIFTH WHEEL (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINFW: 0.00

Job #1 - Warranty

COMPLAINT: FIX SLIDE ROOM SO IT DOES NOT TEAR THE FLOOR ANY MORE

CAUSE: SLIDE ROOM WAS PUCHED TOO CLOSE TOWARDS THR REAR OF THE CAMPER.

CORRECTION: MOVED SLIDE OUT BRACKETS TOWRDS THE BACK SO IT WOULD PULL THE ROOM
TOWARDS THE FRONT OF THE CAMPER. MARKED WITH A PAINT PEN WHERE ADJUSTMENT WAS
MADE. SLIDE ROOM IS CENTERED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	75.00

Subtotal for Job #1: 75.00

Job #2 - Warranty

FIX FLOOR WHERE SLIDE ROOM TORE IT UP



Customer #: 1000
BASDEN'S AMERICAN RV,



SubletDescription
FIBERNEWTotal
325.00**Subtotal for Job #3:****325.00****Job #3 - Warranty**

COMPLAINT: CEILING FAN DOES NOT WORK

CAUSE: CEILING FAN NO COMING ON. CHECKED FOR A FAN SWITCH, CHECKED ALL BREAKERS AND FUSES. REMOVED COVER TO ACCESS WIRES. CHECKED FOR POWER. NOTICED THE POWER WIRE CAME LOOSE FROM WIRE CRIMP CAMP.

CORRECTION: SECURED WIRES. FAN CAME ON. INSTALLED COVER FOR FAN.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	150.00

Subtotal for Job #3: 150.00**Job #4 - Internal**

COMPLAINT: LEVELING SYSTEM IS NOT RESPONDING

CAUSE: WHEN TRYING TO AUTO LEVEL THE MONITOR IS GIVING A MANUAL MODE FAULT. SYSTEM WILL NOT AUTO LEVEL. SYSTEM WILL NOT AUTO RETRACT REAR JACKS. TRIED TO HOME JACKS THROUGH MONITOR PANEL AND IT WOULD NOT DO ANYTHING.

CORRECTION: GOT A FORK TRUCK AND SET UNDER HITCH. MANUALLY HOMED FRONT AND REAR JACKS. PUSHED AUTO LEVEL BUTTON AND ALL THE JACKS ARE NOW RESPONDING. CAMPER DID NOT SIT LEVEL AFTER AUTO LEVEL WAS COMPLETE. MANUALLY LEVELED CAMPER AND RESET ZERO POINT CALIBRATION. ALL FUNCTIONS ON LEVELING SYSTEM ARE WORKING

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #4: 0.00

Parts Total: 0.00

Labour Total: 225.00

Sublet Total: 325.00

Extras Total: 0.00

WORK ORDER TOTAL: 550.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 04 Aug 2022

W/O: 67
Promis Date: 30 JUL 22Customer #: 1000
BASDENS AMERICAN RV,