

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 67834
MANUFACTURER'S CLAIM #:

Manufacturer: 52215 - ALLIANCE RV, LLC
Customer: 41423 - JEFFREY CURL
Address: 7113 OLD BOONVILLE HWY EVANSVILLE, IN

47715

Phone: 812-306-7594

Stock Number: 11187 - 2022 VALOR 40V13 7M5FV4536NA005786

VIN: 7M5FV4536NA005786 HIN:

SER#: 7M5FV4536NA005786

Mileage: 0

Work Order Comp: 23 AUG 22

Auth. No:

Dealer #:

Warr. Date: 18 JUN 22

Work Order Date: 27 JUN 22

Inv #: 381647

WO # Job # Description JOB INFORMATION

67834 2 REAR BLACK TANK CABLE VALVE IS STICKING
CHECK BLACK TANK DRAIN VALVE IS NOT CLOSING ALL THE WAY, SET UP
AND PUT FLUSHER DOWN TOILET, ROD FOR CABLE WITH HANDEL HAS A BEND
IN IT, BLACK TANK VALVE NEED NEW CABLE ASEMBLE, CABLE NEEDS TO BE
ROUTED WITH NO HARD BENDS TO WORK bring unit back in drain
tanks, cut underbelly and found space beteen FRAME AND FREASH
TANK IS OLY 9 INCES, REMOVE OLD VALVE AND CABLE INSTALL NEW VALVE
AND CABLE WILL NOT WORK ODER A NEW VALVE AND CABLE, DRILL NEW
HOLE IN FRAME BEHIND FRASH TANK SO WILL HAVEPROPPER SPACE SO
CABLE WILL NOT HAVE HARD BEND INT

67834 3 THERE IS A CLEAR SEALANT PEELING OFF OF THE FRONT OF THE NOSE
CAP.
finish pealing off loose sealer on bottom of left side above 5th
wheel, and around gen door use silacon and cap seal as needed

67834 4 THE OFF DOOR BEDROOM SLIDE FRAME IS PULLING AWAY FROM THE
FIBERGLASS IN THE FRONT.
FRONT BEDROOM SLIDEROOM ON FRONT SIDE IS PULLING SCREWS OUT OF
THE WALL AND PULLING ON THE FIBEGLAS WALL FROM STUDS, mounting
screws over torked and broken
FRONT BEDROOM SLIDEROOM ON FRONT SIDE IS PULLING SCREWS OUT OF
THE WALL AND PULLING ON THE FIBEGLAS WALL FROM STUDS drill poilet
holes in beteewn broken scews and install new screws after
painting heads black, cap seal as needed wit silacone

Claim : 67834

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
67834      1      THE TELEVISION/FIREPLACE SLIDE DOES NOT GO ALL THE WAY OUT NOR
                DOES IT GO ALL THE WAY IN.
                BRING IN UNIT, FOUND SLIDEROOM SWINTECK HAS JUMPING GREARS WORK
                SLIDEROOM OUT AND DISASSEMBLE SWINTECK SYSTEMS AND INSPECT FOUND
                SEALER ON GEAR TRACKS CLEAN OFF AND REASSEMBLE SWINTECKS TEST
                ASEMBLES WITH TEST CABLE EACH ASEMBLY RUNS SMOOTH, INSTALL ON
                SLIDROOM, SLIDEROOM IS DRAGING ON BOTTOM AND GEARS ARE JUMPING
                BOTTOM OF SLIDEROOM WILL NOT CLOSE ALL THE WAY, CONTROLLER FOR
                SWINTECK SLIDROOM IS LOCATED UNDER CABINET BEHIND SLIDEROOM WHEN
                ROOM IS IN ANY CONTROLLER CAN NOT BE ACCESS, ONLY WHEN ROOM IS OUT
                ALL THE WAY, THIS ROOM NEED ROLLER AND NEW SWINTECK SYSTEM,

```

```

*****
Part No    Job#   Description      PARTS      Qty      Price      Total
*****
10654      2      Valve - Termination - 3 - w/96" C  1.00      47.99      47.99
500627     3      CLEAR SIKASIL PLUS                1.00      19.99      19.99
366154     4      FIXED SIDE DUAL RACK REPAIR KIT    1.00     334.99     334.99
366156     4      FLOAT SIDE - DUAL RACK REPAIR KIT  1.00     334.99     334.99
379060     4      STANDARD BEARING BLOCK KIT         2.00      71.99     143.98

```

```

*****
Lab Code   Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        1.00     150.00     150.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        1.00     150.00     150.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.50     150.00      75.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      2      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      3      MISC LABOUR CODE (EXTERNAL)        0.50     150.00      75.00
Z990      4      MISC LABOUR CODE (EXTERNAL)        1.50     150.00     225.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        1.00     150.00     150.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        1.00     150.00     150.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)        0.00     150.00      0.00

```

Claim : 67834

```

*****
Lab Code  Job#  Description      LABOUR      Hrs      Rate      Total
*****
Z990      1    MISC LABOUR CODE (EXTERNAL)      0.00     150.00      0.00
Z990      1    MISC LABOUR CODE (EXTERNAL)      1.00     150.00     150.00

```

```

*****
Excode    Job#  Description      EXTRAS      Qty      Price      Total
*****
FRT       2    UPS-VALVE              1.00      11.84      11.84
SS        1    SHOP SUPPLIES         1.00       0.00       0.00

```

```

Parts Total:      881.94
Labour Total:     1,125.00
Sublet Total:      0.00
Extras Total:      11.84

```

>>>> Claim Total: 2,018.78

Customer Signature: _____

Date: _____