

# e-Authrization

7/26/20  
09:13:48

3-Authrization number PA03201144 Reference no: 68011 Status: Approved Approved by flins Approved date 7/26/2022  
 rving Myne Address VIN Retail sold on

34 Basden's American RV Basden's American RV 4YDTSGL29N311789  
 600 E Baseline Rd  
 Evansville, IN 47725

| Item | Description                  | Sublet | Sub hours | Approved hours | Actual hours | Qty | Base hours | Complaint / Cause / Correction                                                                                                                                  |
|------|------------------------------|--------|-----------|----------------|--------------|-----|------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 1    | 2300114 Entrance Door - h    | 0.00   | 0.20      | 0.20           |              | 1   | 0.20       | Complaint:MAIN DOOR WILL NOT SHUT<br>Cause:MAIN DOOR WOULDNT SHUT DUE TO STRIKING PLATE BEING TO FAR UP<br>Correction:MOVED STRIKING PLATE BACK                 |
| 3    | 3201803A Decorative Wood     | 0.00   | 0.30      | 0.30           |              | 1   | 0.10       | Complaint:WOOD TAPE PEALING ON THE CABINET<br>Cause:WOOD TAPE PEALING ON CABINET<br>Correction:INSTALLED NEW PIECE OF TAPE VCB                                  |
| 4    | 3200114A Door - Interior Hin | 0.00   | 0.30      | 0.20           |              | 1   | 0.20       | Complaint:BATHROOM DOOR NOT LATCHING<br>Cause:BATHROOM DOOR NOT LATCHING DUE TO STRIKEPLARE BEING TO FAR BACK<br>Correction:ADDED WASHERS BEHIND STRIKEPLATE TO |

KRV - Labor time approved in accordance with Keystone RV's flat rate manual

3-Authrization number PA03201144 0.70

r paper claims only use one pre-authorization number per warranty claim for  
 rple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim  
 m. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the