

BASDEN RV CENTER, INC D.B.A. AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 68059
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 52802 - FRANCIS T. COOMES
Address: 130 E NEW ALBANY AVE VINCENNES, IN

47591

Phone: 812-899-6721

Stock Number: 10864 - 2022 CHEROKEE WOLF PUP 16PF 5ZT2CKEC9NY023069

VIN: 5ZT2CKEC9NY023069 HIN:

SER#: 5ZT2CKEC9NY023069

Mileage: 0

Work Order Comp: 31 AUG 22

Auth. No:

Dealer #:

Warr. Date: 25 JUN 22

Work Order Date: 25 JUL 22

Inv #: 382565

WO # Job # Description JOB INFORMATION

68059 1 THE SLIDE ROOM ONLY ONE SIDE COMING IN AND THE OTHER SIDE DOES
NOT
find unit and bring in, test slideroom room will not moveinside
unit trin boards on slideroom are on floor, on out side back side
of unit, the top of slideroom is closed and the bottom is out 2
in, try to move room through the controler will not move,
disconet wires from controler with power on red and black wires
room will not move, remove screws from swinteck and outside wall
lower screw able to use screw gun, top 4 had to use vice grips on
the heads and unscrew 1/3 turn at time, some of the screw heads
popping off, work room on back side of unit out of hole and
disassemble swinteck, works, bottom block is jamed up and will not
move get fix side out too get screws out of and disassemble
swinteck put unit in walk through untill parts come in bring unit
back in shop, get parts from parts room, asemble swinteck slides,
install on slideroom, and unit wall,, test run, room dose not
move both ends at same time will not reset timming (room runs
in 4 in. and fix side stops flot side contenes to run, 3 more in
and fix side starts to run and room comes in at an angal) go to
new lot find control board remove from unit and bring in wire up
and test room work right, remove board turn in new parts order
for control board, remove new board and return to unit and
install in new unit, wire up bad board

68059 2 THE MICROWAVE IS LOOSE IN IT'S COMPARTMENT.
found screw was over torked and pulled out of microwave, one back

Claim : 68059

 WO # Job # Description JOB INFORMATION

foot is missing off of microwave causing microwave to not sit on
 shelf, turn in PO for new microwave
 REPLACED MICROWAVE

68059 3 STOVE VENT FELL OFF CHECK AND ADVISE
 hood vent off and flapper is broken,
 hood vent off and flapper is broken, check with parts do not have
 turn in PO remove old vent and clean sealer off metal install new
 vent and capseal with silacone

 Part No Job# Description PARTS Qty Price Total

V000481059	1	SLIDEROOM SYSTEM (RACK)		1.00	820.92	820.92
F100141062	2	MICROWAVE, CONTOURE - BLACK RV-98		1.00	161.29	161.29
20X57795A	3	RANGE VENT, EXTERIOR, 1 1/2" WITH		1.00	5.39	5.39

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.28	150.00	42.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.72	150.00	108.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		3.00	150.00	450.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		1.00	150.00	150.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	150.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	150.00	45.00
				0.00	150.00	0.00

 Excode Job# Description EXTRAS Qty Price Total

FRT	2	UPS MICROWAVE AND VENT		1.00	29.30	29.30
-----	---	------------------------	--	------	-------	-------

Parts Total: 987.60
 Labour Total: 840.00
 Sublet Total: 0.00
 Extras Total: 29.30

>>>> Claim Total: 1,856.90

Customer Signature: _____

Date: _____

Claim : 68059

```

*****
Excode   Job#  Description      EXTRAS                      Qty    Price    Total
*****

```