



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68061
Promised Date: 30 JUL 22

CUSTOMER WORK ORDER

WO #: 68061

Customer: 52193 - SPIEHLER, MARK -
812-319-2757

Tag:

Author: BJW

Location: 0810 CHECK PARTS

Stock #: 10995

Stock Desc: 2022 TT COACHMEN APEX
265RBSS

Chassis #: 5ZT2CXSBB1NS042985

Serial #: 5ZT2CXSBB1NS042985

Mileage: 0

Licence:

Invoice #:

Date In: 25 JUL 22

Promised: 30 JUL 22

Date Sched:

Completed: 06 AUG 22

Warr. Date: 21 JAN 22

Job #1 - Warranty

COMPLAINT: THE SEAL ALONG THE BOTTOM OF THE SHOWER PAN IS LEAKING. WATER RUNS OUT ONTO THE FLOOR WHEN TAKING A SHOWER.

CORRECTION: REMOVED FACTORY SILICONE AND REPLACED WITH NEW SILICONE. checked for leaks, non was found

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	45.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Subtotal for Job #1: 45.00

Job #2 - Warranty

COMPLAINT: THE BLIND NEXT TO THE DINNETTE WON'T STAY UP.

CORRECTION: TIGHTENED THE STRING

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	15.00

Subtotal for Job #2: 15.00

Job #3 - Warranty

COMPLAINT: THE TRIM ON THE REAR EDGE OF THE SLIDE ROOM IS LOOSE.

CORRECTION: BLACK TRIM WAS COMING OFF TOOK PICTURES. SHOT STAPLES IN TRIM TO FIX THIS ISSUE. OTHER TRIM IS PEELING THE PAPER COATING OFF. PUT IN PO FOR WARRANTY ON TRIM

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JP	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00

Parts

Part #	Description	Qty	Price	Total
F100247245	FASCIA, INSERT 1/8X1.475X97	1.00	1.76	1.76
	STIPPLE SAND BLACK HDBD NAUF SE			

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-TRIM	1.00	154.89	154.89



Customer #: 52193
SPIEHLER, MARK

Subtotal for Job #3: 186.65

Parts Total: 1.76
Labour Total: 90.00
Sublet Total: 0.00
Extras Total: 154.89

WORK ORDER TOTAL: 246.65

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Aug 2022

W/O: 68061
Promised Date: 30 JUL 22



Customer #: 52193
SIEHLER, MARK

