



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68079
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68079 (Appointment Date: 27 JUL 2022 - Time: 07:00am)

Customer: 46455 - WILL, MICHELE L. -
812-483-6540

Stock #: 11058

Stock Desc: 2022 TT RIVERSIDE RV

Invoice #:

Date In: 26 JUL 22

Tag

INTREPID 240DDS

Promised: 31 AUG 22

Author: BJW

Chassis #: 59CCC3627NL004596

Date Sched:

Location: 0829 GET WITH CHRIS IF NO
RSPONCE FROM RIVERSIDE

Serial #: 59CCC3627NL004596

Completed: 29 AUG 22

Mileage: 0

Warr. Date: 09 JUN 22

Licence:

Job #1 - Warranty

COMPLAINT: WHEN THE FRESH TANK IS FILLING , WATER IS GUSHING OUT FROM THE UNDERBELLY.

CAUSE: THE FRESH WATER HOSE HAD A CRACK IN IT.

CORRECTION: I THINK MATT HAS ALREADY ORDERED A NEW HOSE FOR ME WHEN HE ORDERED ONE FOR RYAN

FRESH WATER TANK FILL HOSE HAD A CRACK IN IT COMING OUT OF THE TANK. CUT UNDER BELLY AT FRONT AND BACK AND FISHED NEW HOSE THROUGH THE UNDER BELLY AND RECONNECTED. REPAIRED UNDER BELLY.

Labor

Ccode	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	30.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00

Parts

Part #	Description	Qty	Price	Total
195348	1.25" WATER FILL HOSE	12.00	1.28	15.36

Other Services

Ccode	Description	Qty	Price	Total
FRT	UPS-FILL HOSE	1.00	21.29	21.29

Subtotal for Job #1: 66.65

Job #2 - Internal

COMPLAINT: CUSTOMER WAS ON A RECENT CAMPING TRIP. THE OUT SIDE TEMP WAS 91. IT WAS 98 INSIDE THE CAMPER. THE COOLEST THAT THE A/C GOT THE COACH WAS 75 THROUGH THE NIGHT.

CORRECTION: THE VENTS ON CEILING UNIT WERE OPEN AND GIVING A FALSE READING TO THERMOSTSTE. THE VENTS ON THE CEILING UNIT MUST BE CLOSED SO AIR FLOWS THROUGH THE CEILING DUCT VENTS.

Labor

Ccode	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C



Customer #: 46455
WILL, MICHELE L.



Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: THE WINDOW LATCH ON THE DOOR SIDE BEDROOM WINDOW BROKE OFF.

CAUSE: WINDOW LATCH IS BROKEN.

CORRECTION: IF WE CAN ORDER JUST THE LATCH HANDLE FOR THE WINDOW I CAN REPLACE IT. OR MAYBE HAVE TO ORDER A NEW WINDOW?

REMOVED OLD WINDOW AND INSTALLED NEW WINDOW. CALKED WINDOW AND CLEANED IT.

Labor

Ccde	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	150.00

Subtotal for Job #3: 150.00

Job #4 - Warranty

COMPLAINT: THE FREEZER DOOR WILL NOT STAY CLOSED WHILE TRAVELING. FRIDGE DOES FINE

CORRECTION: ADJUSTED HING ON FREEZER DOOR. LATCH WORKS NOW AND DOOR STAYS CLOSED

Labor

Ccde	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	15.00

Subtotal for Job #4: 15.00

Job #5 - Internal

COMPLAINT: THE AWNING ON TOWARDS THE FRONT STAYS DOWN LIKE IT WOULD BE WHEN YOU PULL IT DOWN TO DRAIN THE RAIN WATER ALL THE TIME.

CORRECTION: THE SHOCK ON THE LEFT AWNING ARM WAS BAD. I REPLACED THE SHOCK AND THE AWNING OPERATES AS IT SHOULD.

Labor

Ccde	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #5: 0.00

Parts Total:	15.36
Labour Total:	195.00
Sublet Total:	0.00
Extras Total:	21.29
WORK ORDER TOTAL:	231.65

W/O: 68079
Promised Date: 31 AUG 22



Customer #: 46455
WILL, MICHELE L.

