

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106 BASDEN RV CENTER INC DBA AMERICAN RV CENTER 600 E BASELINE ROAD EVANSVILLE, IN 47725 USA	CLAIM STATUS Authorized CLAIM 1161963 CLAIM ORIGIN WEB ORIGINAL CLAIM ID VIN 5ZT2CAVB3NX024693 CHASSIS VIN MILEAGE 0 SITE/WAREHOUSE 205 / 205 ITEM # ACAT303RKDSLE DEALER RO # 68087 CLAIM START DATE 07/28/2022 CLAIM END DATE 01/01/1900	
Labor rate: \$150.00 OWNER INFORMATION DENNIS A SUTTON 2317 JULIANNE CR Newburgh, IN 47630 USA		
Retail Date of Purchase 05/20/2022	WARRANTY EXPIRATION DATE 05/20/2023	

Claim Line Details

Labor

Line# 1	Operation Code RC-026-01-00-004186	Operational Description 22V243, 2022-181 - FLEXTech QUICK DISCONNECTS - REMEDY (INCLUDES INSPECTION) - Recall/LP Gas System/Replace/No Tread Code								
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-07-28 10:52:19 :: RECALL 22V243 LP QUICK CONNECT verified that the quick connect was warranty then removed and replaced with new quick connect									
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.30</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$45.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.30</td> <td>Appr Labor Amt</td> <td>\$45.00</td> </tr> </table>	Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00	Appr Hrs	0.30	Appr Labor Amt	\$45.00
Dlr Sub Hrs	0.30	Sub Labor Amt	\$45.00							
Appr Hrs	0.30	Appr Labor Amt	\$45.00							
	Notes aAUTHORIZED AS REQUESTED									

Labor

Line# 2	Operation Code 20-73-24-00-000739	Operational Description Fenderskirt - Exterior/Fender Skirts, Wheel Well/Repair/No Tread Code								
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-07-28 10:54:56 :: THERE IS TRIM MISSING IN THE BOTTOM OF THE BEDROOM SLIDE. ONE PIECE OF TRIM WAS MISSING FOR TH J WRAP. PUT A NEW PIECE OF TRIM IN PLACE									
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.40</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$60.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.40</td> <td>Appr Labor Amt</td> <td>\$60.00</td> </tr> </table>	Dlr Sub Hrs	0.40	Sub Labor Amt	\$60.00	Appr Hrs	0.40	Appr Labor Amt	\$60.00
Dlr Sub Hrs	0.40	Sub Labor Amt	\$60.00							
Appr Hrs	0.40	Appr Labor Amt	\$60.00							
	Notes aAUTHORIZED AS REQUESTED									

Labor

Line# 3	Operation Code 40-106-01-11-001246	Operational Description 7-Way Cord - Tow Vehicle Power - Electrical/12 Volt Exterior/Replace/ Electrical								
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2022-07-28 10:56:46 :: CHECK THE ELECTRICAL WIRING COVER NEAR THE END THAT PLUGS INTO THE TRUCK. THERE ARE WIRES SHOWING. PUT IN A PO FOR NEW 7 PIN TRAILER PLUG.									
	Model # Serial #	<table border="0" style="width: 100%;"> <tr> <td style="width: 30%;">Dlr Sub Hrs</td> <td style="width: 10%;">0.50</td> <td style="width: 30%;">Sub Labor Amt</td> <td style="width: 30%;">\$75.00</td> </tr> <tr> <td>Appr Hrs</td> <td>0.50</td> <td>Appr Labor Amt</td> <td>\$75.00</td> </tr> </table>	Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00	Appr Hrs	0.50	Appr Labor Amt	\$75.00
Dlr Sub Hrs	0.50	Sub Labor Amt	\$75.00							
Appr Hrs	0.50	Appr Labor Amt	\$75.00							
	Notes aAUTHORIZED AS REQUESTED									

Submitted

Labor Amt	\$180.00
Parts & Freight	\$0.00
Total	\$180.00

Approved

Labor Amt	\$180.00
Parts & Freight	\$0.00
Total	\$180.00

DEALER

SIGNATURE

DATE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

SIGNATURE

DATE

All repairs described have been inspected and are satisfactory.