

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 80126
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11769 - 2027 COUGAR HALF-TON 22MLS 4YDTCGK21VV500011
VIN: 4YDTCGK21VV500011 HIN: SER#: 4YDTCGK21VV500011
Mileage: 0 Work Order Comp: 27 AUG 26
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 03 JUN 26 Inv #: 434254

WO # Job # Description JOB INFORMATION

80126 4 SCRATCH ON FREEZER DOOR
Door scratched
During pdi noticed a scratch on the freezer door. Pictures taken
parts request submitted
80126 2 BATHROOM TRIM DAMAGED
Trim
During pdi noticed trim in bathroom over wood had damage.
Pictures taken. Partd request submitted
80126 6 STILE UNDER FRIDGE BROKEN
Stile
During pdi notcied stile under fridge had split. Pictures taken.
Parts request submitted
80126 8 SCRATCH ON MICROWAVE TRIM RING
Trim ring
During pdi notcied a scratch on the trim ring mounting microwave.
Picutre taken. Parts request submitted
80126 1 BLACK TANK MISSING HANDLE
Tank handle
During pdi notcied blaxk tank was missing handle. Placed new
handle on and secured
80126 7 HOLES IN AWNING FABRIC

Claim : 80126

 WO # Job # Description JOB INFORMATION

Awning

During pdi fabric came in folded when brought to us. Ran awning out and saw holes starting to form and creases pulling on stitching of fabric. Pictures taken. Parts request submitted

80126 9 A/C PLENUM LOOSE AND HANGING
 Plenum hanging loose
 During pdi noticed ac plenum hanging in ceiling. Pictures taken. Took cover off and saw no screws had been placed to secure to ceiling. Went and found screws and secured in place.

 Part No Job# Description PARTS Qty Price Total

 757048 4 Refrigerator - Freezer Door Assem 1.00 189.92 189.92
 762433 2 Trim - End Cap - 3/16" x 10' - 60 1.00 2.05 2.05
 759641 6 Stile - Square - 18mm x 2" x 96" 1.00 10.54 10.54
 678394 8 Microwave - Trim Kit - .9 Cu Ft - 1.00 11.86 11.86
 24478 1 VALVE HANDLE - METAL 1.00 6.90 6.90
 752455 7 Awning - 16' - 3000 Series - Sole 0.00 543.95 0.00
 13411 7 PLASTI DIP VLP REPAIR ADHESIVE 1.00 16.21 16.21

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 4 MISCELLANEOUS REPAIR 0.20 190.00 38.00
 Z990 4 MISCELLANEOUS REPAIR 0.10 190.00 19.00
 Z990 4 MISCELLANEOUS REPAIR 0.20 190.00 38.00
 Z990 2 MISCELLANEOUS REPAIR 0.10 190.00 19.00
 Z990 2 MISCELLANEOUS REPAIR 0.00 190.00 0.00
 Z990 6 MISCELLANEOUS REPAIR 0.30 190.00 57.00
 Z990 6 MISCELLANEOUS REPAIR 0.00 190.00 0.00
 Z990 6 MISCELLANEOUS REPAIR 0.00 190.00 0.00
 Z990 6 MISCELLANEOUS REPAIR 0.00 190.00 0.00
 Z990 8 MISCELLANEOUS REPAIR 0.17 190.00 32.30
 Z990 8 MISCELLANEOUS REPAIR 0.03 190.00 5.70
 Z990 1 MISCELLANEOUS REPAIR 0.25 190.00 47.50
 Z990 1 MISCELLANEOUS REPAIR 0.25 190.00 47.50
 Z990 7 MISCELLANEOUS REPAIR 0.39 190.00 74.10
 Z990 7 MISCELLANEOUS REPAIR 0.11 190.00 20.90
 Z990 9 MISCELLANEOUS REPAIR 0.30 190.00 57.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 2 FREIGHT - JOBS 2,6 1.00 139.10 139.10
 FRT 8 UPS-JOB 8 1.00 39.79 39.79
 FRT 7 SHIPPING-VLP 1.00 5.22 5.22

Claim : 80126

```
*****
Excode   Job#   Description      EXTRAS                Qty    Price    Total
*****
```

```
Parts Total:      237.48
Labour Total:     456.00
Sublet Total:       0.00
Extras Total:     184.11
```

```
>>>> Claim Total:      877.59
```

Customer Signature: _____

Date: _____