

BASDEN RV CENTER, INC D.B.A. AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 68112  
MANUFACTURER'S CLAIM #:

Manufacturer: 49672 - RIVERSIDE RV  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11233 - 2023 RETRO 210 59CCC2322PL006449

VIN: 59CCC2322PL006449 HIN:

SER#: 59CCC2322PL006449

Mileage: 0

Work Order Comp: 19 SEP 22

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 29 JUL 22

Inv #: 382781

\*\*\*\*\*

WO # Job # Description JOB INFORMATION

\*\*\*\*\*

68112 1 FIX CAMPER WHERE THE METAL IS DAMAGED  
REPLACE DAMAGED METAL ON BOTTOM OF SLIDE OUT. REPLACE METAL ON  
FRONT OF SLIDE PUT NEXT TO WINDOW. REPLACE SLIDE OUT FACIA TRIM  
ON BOTH SIDES. REPLACE DECALS ON REAR CORNER. REPLACE METAL ON  
DOOR SIDE FRONT CORNER. METAL WAS SCRATCHED AND DENTED DURING  
SHIPPING. TOLD DENNY AND MATT ABOUT DAMAGE. WAS ADVISED TO  
REPLACE METAL.  
PULLED UNIT INTO SHOP. WENT AND FOUND PARTS FOR REPAIR. REMOVED  
PARTS FROM CRATE'S. FOUND THAT THE "BLUE" PIECES OF METAL WERE  
SRATCHED AND DENTED IN SEVERAL PLACES AND ONE OF THE DECALS WAS  
CREASED. WILL HAVE TO CUT AROUND SCRATCHES AND DENTS. WENT TO THE  
REAR DRIVERS SIDE AND CUT THE SILICONE AROUND THE BLUE CORNER  
DECAL AND THE DECAL THAT GOES OVER IT. REMOVED THE SHORE POWER  
CORD INLET AND THE COAX INLET. REMOVED BOTH DECALS. INSTALLED NEW  
DECALS. SEALED EDGE OF DECALS WITH SILICONE. INSTALLED SHORE  
POWER INLET AND COAX INLET. SEALED THOSE WITH SILICONE. WENT TO  
SLIDE OUT. REMOVED SLIDE OUT FACIA CORNER COVERS. CUT ALL  
SILICONE AROUND FACIA TRIM. REMOVED SCREWS FROM TRIM. REMOVED  
TRIM AND SET TO THE SIDE. REMOVED FENDER SKIRT OFF BOTTOM PIECE OF  
METAL. REMOVED METAL AND SET TO THE SIDE. GOT NEWPIECE OF METAL  
AND CUT TO LENGTH. CUT OUT SECTION FOR FENDER SKIRT. INSTALLED  
NEW METAL AND SECURED TO SLIDE AND SUPPORT. INSTALLED FENDER  
SKIRT. HAD TO TRIM SOME MORE AROUND FENDER. SEALED FENDER SKIRT  
WITH SILICONE. WENT INSIDE UNIT AND REMOVED VALANCE AND BLINDS.  
REMOVED SCREWS AND INSIDE RING FROM WINDOW. REMOVED WINDOW. WENT  
OUTSIDE AND PULLED METAL DOWN OUT OF TRACK. REMOVED SCREWS AND

Claim : 68112

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*  
 METAL. CUT NEW METAL TO LENGTH. INSTALLED METAL AND SECURED WITH  
 SCREWS. INSTALLED WINDOW. INSTALLED BLINDS AND VALANCE. TAPED OFF  
 WINDOW. SEALED OUT SIDE OF WINDOW WITH SILICONE. TOOK NEW FACIA  
 TRIM AND CUT TO LENGTH AND CUT A 45 DEGREE ANGLE AT THE TOP.  
 INSTALLED FACIA TRIM.TAPED OFF AND SEALED WITH SILICONE.  
 INSTALLED CORNER CAPS. SEALED CAPS WITH SILICONE. TOOK ROOF TAPE  
 AND WENT OVER CORNERS AT TOP OF SLIDE OUT FACIA. WENT TO FRONT  
 DOOR SIDE CORNER AND CUT SILICONE AROUND FRONT CONER TRIM.  
 REMOVED SCREWS AND PULLED UP TRIM. REMOVED COMPARTMENT DOOR.CUT  
 SILCONE AROUND ENTRY DOOR. REMOVED SCREWS FROM RIGHT SIDE OF  
 ENTRY DOOR NEAR THE METAL. REMOVED BOTTOM PIECE OF METAL. OPENED  
 AWNING AND REMOVED THE BOTTOM AND MIDDLE MOUTING BOLTS. TOOK A  
 WOODEN BLOCK AND PLACED UNDER AWNING ARM TO PUSH ARM AWAY FROM  
 METAL. CUT NEW PIECE OF METAL TO LENGTH. INSTALLED METAL TO WALL.  
 CUT OUT HOLE FOR COMPARTMENT DOOR. INSTALLED LOWER PIECE OF  
 METAL. INSTALLED FROM CORNER TRIM. SEALED WITH SILICONE.  
 INSTALLED DOOR SCREWS AND SEALED AREA WITH SILICONE. INSTALLED  
 FOAM ON COMPARTMENT DOOR. INSTALLED DOOR. SEALED DOOR WITH  
 SILICONE. REMOVED WOOD FROM BEHIND AWNING ARM. INSTALLED LAG  
 BOLTS FOR AWNING. CLEANED UP BAY. FILLED OUT NOTES.

\*\*\*\*\*  
 Part No      Job#      Description      PARTS      Qty      Price      Total  
 \*\*\*\*\*  
 500627      1      CLEAR SIKASIL PLUS           1.00      8.51      8.51

\*\*\*\*\*  
 Lab Code      Job#      Description      LABOUR      Hrs      Rate      Total  
 \*\*\*\*\*  
 Z990      1      MISC LABOUR CODE (EXTERNAL)           1.20      150.00      180.00  
 Z990      1      MISC LABOUR CODE (EXTERNAL)           1.69      150.00      253.50  
 Z990      1      MISC LABOUR CODE (EXTERNAL)           3.31      150.00      496.50  
 Z990      1      MISC LABOUR CODE (EXTERNAL)           1.20      150.00      180.00  
 Z990      1      MISC LABOUR CODE (EXTERNAL)           0.00      150.00      0.00

Parts Total:      8.51  
 Labour Total:      1,110.00  
 Sublet Total:      0.00  
 Extras Total:      0.00

>>>> Claim Total:      1,118.51

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_