



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 68114
Promised Date: 31 AUG 22

CUSTOMER WORK ORDER

WO #: 68114

Customer: 52900 - RAUCH,
CHRISTOPHER - 812-484-5281

Tag:

Author: BH

Location: 1004 CHECK PREAUTH

Stock #: 10880

Stock Desc: 2022 TT FOREST RIVER

CHEROKEE WOLF PUP 17JG

Chassis #: 5ZT2CKFC0NY022262

Serial #: 5ZT2CKFC0NY022262

Mileage: 0

Licence:

Invoice #:

Date In: 29 JUL 22

Promised: 31 AUG 22

Date Sched:

Completed: 30 SEP 22

Warr. Date: 29 JUL 22

Job #1 - Warranty

COMPLAINT: DENT IN FRONT DOOR SIDE COMPARTMENT
DOOR FRAME 28"X16"

CORRECTION: TOOK OUT DOOR AND INSTALLED NEW DOOR AND SEALED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	75.00

Parts

Part #	Description	Qty	Price	Total
5952	15.75 X 27.75 COMP DOOR - BLACK	1.00	31.97	31.97

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT - ALL JOBS	1.00	68.78	68.78

Subtotal for Job #1: 175.75

Job #2 - Warranty

COMPLAINT: DOOR SIDE FRONT WINDOW - 24X15
HORIZONTAL SLIDER HAS DENT IN FRAME.

CORRECTION: TOOK OFF BLIND AND CAP FOR WINDOW, TOOK OUT SCREWS IN WINDOW AND PULLED OUT WINDOW, PUT FOAM AROUND WINDOW AND INSTALLED WINDOW, PUT IN BEAUTY RING AND INSTALLED SCREWS AND SEALED OUTSIDE, CLEANED WINDOW AND INSTALLED BLIND AND CAP.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00

Parts

Part #	Description	Qty	Price	Total
20X34838A	WINDOW, 24" X 15" HORIZONTAL SLIDE - CLEAR SAFETY GLASS/BLACK FRAME SHED	1.00	59.58	59.58

Subtotal for Job #2: 209.58

Job #3 - Warranty

COMPLAINT: DOOR SIDE WINDOW NEAR MIDDLE OF UNIT
HAS DAMAGED FRAME

CORRECTION: TOOK BLIND OFF AND TOP TRIM PIECE, TOOK SCREWS OUT OF WINDOW AND



Customer #: 52900
RAUCH, CHRISTOPHER



PULLED WINDOW, PUT FOAM AROUND NEW WINDOW AND INSTALLED WINDOW AND TRIM RING, SEALED TOP OF WINDOW AND CLEANED WINDOW, PUT UP WINDOW TREATMENT AND BLIND BACK IN PLACE.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	150.00

Parts				
Part #	Description	Qty	Price	Total
20X34838A	WINDOW, 24" X 15" HORIZONTAL SLIDE - CLEAR SAFETY GLASS/BLACK FRAME SHED	1.00	59.58	59.58
5460	BLACK PUTTY TAPE 1" X 20'	1.00	6.27	6.27
Subtotal for Job #3:				215.85

Job #4 - Warranty

COMPLAINT: GUTTER OVER DOOR SIDE "BUNK" DOOR IS BENT/CROOKED.

CORRECTION: TOOK OFF TRIM AND RESET ON DOOR AND SEALED.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00

Parts				
Part #	Description	Qty	Price	Total
F100059332	29.5" DRIP RAIL FOR	1.00	2.28	2.28
Subtotal for Job #4:				47.28

Job #5 - Warranty

COMPLAINT: COMP. DOOR FOR OUTSIDE REFER IS STICKING OUT ON LOWER LEFT CORNER. SOMETHING IN THE WAY KEEPING IT FROM BEING FLUSH.

CORRECTION: TOOK OUT REF TO GET DOOR FROME OUT, BENT METAL PAN BACK IN PLACE AND REINSTALLED DOOR FRAME AND RESEALED AND PUT REF BACK IN.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	75.00
Subtotal for Job #5:			75.00

Job #6 - Warranty

COMPLAINT: THE SLIDE WOULD NOT GO OUT. CUSTOMER WORKED OM UNIT AND GOT THE SLIDE TO GO OUT. IT DID COME IN, BUT IT STILL STICKS OUT A LITTLE ON THE LOWER REAR CORNER.

CORRECTION: TOOK PICTURES AND MEASUREMENTS AND FILLED OUT SHEET TO GET APPOROVAL AND FILLED OUT PARTS REQUEST SHEET. GAVE TO MATT TO ORDER. REPLACED SCHWINTECK RACK SYSTEM ON SLIDE ROOM. ALSO I REPAIRED INSIDE LEFT SIDE OF OF SLIDE ROOM IT WAS DRAGING WHEN OPERATING THE SLIDE ROOM.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00





Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	150.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	600.00

Parts

Part #	Description	Qty	Price	Total
6544	SLIDEROOM SYSTEM (RACK)	1.00	823.65	823.65

Subtotal for Job #6: 1,573.65

Job #7 - Internal

COMPLAINT: CUSTOMER NOTICED WATER ON TOP OF THE SLIDE ROOM PRIOR TO RUNNING ROOM OUT. IT WAS RAINING WHEN THIS WAS NOTICED, BUT THE ROOM HAD NOT BEEN RAN OUT YET.

CORRECTION: INSPECTED UPPER BULB SEAL AND EVERYTHING LOOKED GOOD. PROBLEM WAS POSSIBLY CAUSED BECAUSE SLIDE ROOM WOULD NOT GO IN ALL THE WAY.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DWW	N/C

Subtotal for Job #7: 0.00

Job #8 - Internal

COMPLAINT: CUSTOMER NOTICED THAT THE DOOR SIDE TAILLAMP IS NOT WORKING THE SAME AS THE OFF DOOR LAMP

CORRECTION: HOOKED UP BOX AND CHECKED LIGHTS ALL IS GOOD.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	N/C

Subtotal for Job #8: 0.00

Job #9 - Warranty

COMPLAINT: BED SUPPORTS BROKEN

CORRECTION: TOOK OFF PLASTIC TRIM AND HANDLE, TOOK OUT BROKEN BOARD AND CUT NEW BOARD AND PUT IN PLACE AND STAPLED THE TOP DOWN, PUT PLASTIC BACK ON AND HANDLE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	75.00

Subtotal for Job #9: 75.00

Job #10 - Warranty

COMPLAINT: THE OUTER RIGHT REAR CORNER TRIM IS LOOSE.

CORRECTION: TOOK INSERT OUT AND SHOT MORE SCREWS IN AND SEALED.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	DGH	45.00

Subtotal for Job #10: 45.00



W/O: 68114
Promised Date: 31 AUG 22

Parts Total:	983.33
Labour Total:	1,365.00
Sublet Total:	0.00
Extras Total:	68.78
WORK ORDER TOTAL:	2,417.11

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 03 Oct 2022



Customer #: 52900
RAUCH, CHRISTOPHER

